

» Overview

Order number: 1002366136
Order completed: 17.03.2026 11:17
Report number: 10239215
VIN: WVVZZZ3CZNE038611



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	EstateCar
Make:	Volkswagen
Model:	Passat
Manufacturers and type code:	0603 / CON
Date of first registration:	10.02.2022
Mileage:	68,732 km
Proof of mileage:	ReadOff
Exterior colour:	Mondsteingrau
Roof colour:	Mondsteingrau
Propulsion:	Front
Fuel:	Diesel
Engine size (cc):	2,000 ccm
Performance:	147 kW (200 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining fabrics
Interior colour:	Titanschwarz/Titanschwarz/Titanschwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	

"Business Premium" package incl. navigation system	Disc brakes in front
12-V outlet in center console rear and in luggage compartment	Disc brakes in rear
2 beverage holders in front with cover	Diversity antenna for FM reception
2 USB-C ports in the front, 1 USB-C charging socket on the center console in the rear	Door and side trim panel in foam film and woven fabric
230-V outlet in center console in rear	Driver alert system
3 head restraints in rear	Driver and front passenger airbag with front passenger airbag deactivation
3-point seat belt for center rear seat	Driving on the right
3-point seat belts for outer rear seats	Dual-clutch transmission DSG DQ381
3-point seat belts in front with height adjustment and seat belt pretensioners	Dynamic Road Sign Display
4 alloy wheels "Istanbul" 7J x 17, painted in Sterling Silver	Electric auxiliary air heater
4-cylinder diesel engine 2.0 l	Electromechanical parking brake with Auto Hold function
4-cylinder diesel engine 2.0 l TDI, 147 kW	Electromechanical speed-sensitive power steering
7-speed automatic or DSG note: family EDF	Electronic engine sound
8 speakers	Electronic immobilizer
Adaptive Cruise Control ACC stop & go incl. speed limiter	Electronic Stability Control and electromechanical brake booster
Air Care Climatronic 3 zone automatic climate control with enhanced air filter and controls in the rear	Elimination of nameplate for engine designation on luggage compartment lid
AirStop® tires 215/55 R17	Elimination of Tire Mobility Set
Alternator 140 A	Emergency call service; no registration required, service is activated upon delivery
App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto	Emission standard EU6 AP
Aspherical exterior mirror on driver side	Equipment options subset for Germany
Aut. headlight control w/ separate daytime running light, Leaving Home and manual Coming Home feature	Exterior mirrors, power-adjustable and heated, surround lighting, auto-dimming on driver side
Auto-dimming interior rearview mirror	First aid kit, warning triangle and safety vest
Automatically-heated washer nozzles in front	Folding luggage compartment floor
Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)	Folding trailer hitch, with electric release
Basic equipment variant	Front center armrest, height- and longitudinally adjustable, w/ storage comp., 2 vents w/ chrome louvers in rear
Battery 420 A (70 Ah)	Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment
Body-colored lower side trims	Front vent and rotary light switch illuminated, with chrome bezel
Bumpers with body-colored decorative trims	Front-wheel drive
Business	Fuel system for diesel engine
Carpet mats in front and rear	Fuel tank with a volume of 66 l
Carrier frequency 433.92 MHz-434.42 MHz	Gearshift knob in leather
Category 0	Headlight range control
Child safety lock	Heated front seats
Chrome trims on the side windows	Hill Start Assist
Comfort seats in front	Illuminated vanity mirror in sun visors, extractable sun visors
Curtain airbag system for front and rear passengers incl. side airbags in front	Initial standard fuel filling
Decorative inserts "Cross Hatch" for dashboard and door trim panels	Inserts of front seats and outer rear seats in fabric "Business"
Decorative inserts "Piano Black" for center console	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
Digital radio reception DAB+	

Interior lights with switch-off delay and dimmer, 2 LED reading lights in front and 2 in rear	Proactive passenger protection system and lane change system Side Assist
ISOFIX anchorage points for mounting 2 child seats on rear seats, also for i-Size child seats	Proactive passenger protection system in combination with Front Assist and Side Assist
Keyless Start without SAFELOCK	Radio
Labels in German	Rain sensor
Laminated safety glass windshield, heat- and sound-insulating	Rear exhaust tailpipe (standard)
Lane change system Side Assist and Rear Traffic Alert	Rear fog light on one side, back-up light on both sides
Leather-wrapped multi-function steering wheel with shifting paddles	Rear shock absorption, basic version 1
LED entry/warning lights in front doors	Rear view camera system
LED front fog lamps and cornering light	Refrigerant R1234yf
LED headlamps with LED separate daytime running light	Regional code " ECE " for radio
LED light unit in front footwell	Remote unlocking for tailgate/trunk lid
LED rear combination lamps	Right exterior mirror, convex
Left-hand drive	Roof rails, silver-anodized
License plate carrier in front and rear (ECE)	Safety-optimized front head restraints, longitudinally and height adjustable
LongLife Service Regime	Semi-automated driving assistance TravelAssist and lane keeping system Lane Assist
Luggage compartment cover extractable and removable	Service indicator 30 000 km or 2 years (variable)
Lumbar supports in front, power- adjustable on driver side, massage feature on driver side	Shock absorption in front
Manual in German (Germany)	Small navigation system M&I (Media & Internet package)
Mass damper for steering wheel, 36 Hz	Special identification label for EC for M1 passenger vehicles
Mistral Gray headliner	Standard battery/alternator capacity
Mobile phone interface "Comfort" with inductive charging feature	Standard climatic zones
Model update, week 45	Standard engine starter
Multifunction camera	Standard manufacturing sequence
Multi-function display "Premium" with multi-color display	Standard paint coating
Navigation system "Discover Media" incl. Streaming & Internet	Standard pedal cluster
Net partition	Standard wheel bolts
No special edition	Start-stop system with generative braking
No special purpose vehicle, standard equipment	Suspension range 34 installation control only, no requirement forecast
Non-folding front passenger seat backrest	Textile luggage compartment lining
Non-smoker's package: tray and 12-V outlet in front	Tire Pressure Monitoring System
Not hot country	Tires without specification of tire brand
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Tool kit
Operating permit, alteration	Transport protection film (minimum protection) with additional transport protection measures
Park Distance Control - warning signals for obstacles in the front and rear	Two-tone horn
Part set without country-specific prescriptive standard	Type approval country Germany
Pedestrian monitoring	Unsplit rear bench seat, asymmetric folding backrest, center armrest with storage comp. and load-through hatch
Plastic loading edge protection	Vehicle class differentiation -3G0-
Plastic scuff plates in door apertures	Vehicles with special upgrade measures
Preparation for We Connect and We Connect Plus	Wagon
Privacy glass for rear side windows and rear window	Warning signal and warning light for front and rear seat belts not fastened

Weight range 4 installation control only, no requirement forecast

Wheelbase

With electronic steering column lock

Without activated carbon canister with SCR

Without Adaptive Chassis Control

Without add. lights (interior lighting)

Without additional front underbody guard

Without additional tires

Without alternative drive system

Without auxiliary heater/parking heater

Without CD/DVD for navigation

Without charging cable

Without child seat

Without clock

Without customized installation

Without delivery equipment

Without differential lock

Without ECO function

Without electric motor (hybrid)

Without fire extinguisher

Without front passenger seat control

Without garage door opener

Without headlamp washer system

Without head-up display

Without integrated toll system

Without light control

Without locking and starting systems

Without preparation for rotating beacon/siren combination

Without preparation for two-way radio installation

Without preparation for VTS (vehicle tracking system)

Without rear spoiler

Without roll-up sunshade

Without roof insert (standard roof)

Without seat ventilation/massage seat

Without second battery

Without special body measures

Without tie down straps/net/pocket

Without vehicle inlet

Without voice control

» Tyres

MOUNTED TYRES

There are currently one or more wheel sets on/in the vehicle that are not included in the scope of delivery.

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental	Front	Left	Winter	Aluminium	215/60 R 16 99 H	5.0 mm
Continental	Front	Right	Winter	Aluminium	215/60 R 16 99 H	5.0 mm
Continental	Rear	Left	Winter	Aluminium	215/60 R 16 99 H	6.0 mm
Continental	Rear	Right	Winter	Aluminium	215/60 R 16 99 H	6.0 mm

Permitted: Yes

Roadworthy: Yes

UNMOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental			Summer	Aluminium	215/55 R 17 94 W	3.0 mm
Continental			Summer	Aluminium	215/55 R 17 94 W	3.0 mm
Continental			Summer	Aluminium	215/55 R 17 94 W	6.0 mm
Continental			Summer	Aluminium	215/55 R 17 94 W	6.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 05.2028

Compressor present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Seat cover FL	Stain	Cleaning

» Usage Damages

Nr	Location	Damage type	Repair type
1	Windscreen	Stone chip(s)	Acceptable
2	Bumper R	Scratch(es)	Acceptable

» Commercial devaluation

Known previous damages:	Yes
Previous damages detectable:	No
Repainting present:	Yes
Repainting professionally executed:	Yes
Paint thickness measurement performed:	Yes - with abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Liability loss		€ 2,446.92
2	Other	Liability loss		€ 4,800.00
3	Other	Fully comprehensive harm		€ 1,500.00
4	Other	Fully comprehensive harm		€ 1,500.00
Total without VAT:				€ 10,246.92

PAINTTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Wing FL (µm)	137.0
Paint thickness Door FL (µm)	150.0
Paint thickness Door RL (µm)	277.0
Paint thickness Wing RL (µm)	203.0
Paint thickness Trunk (µm)	186.0
Paint thickness Wing RR (µm)	201.0
Paint thickness Door FR (µm)	191.0
Paint thickness Door RR (µm)	196.0
Paint thickness Wing FR (µm)	212.0
Paint thickness Bonnet (µm)	204.0
Paint thickness Roof (µm)	214.0

At least 3 measurements were carried out per component.

» Notes On The Assessment**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVWZZZ3CZNE038611

VIN checked and matches documentation

Vehicle condition:

Cleaned

Inspection condition:

Restricted

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Tools



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Additional wheel 1



Additional wheel 2



Additional wheel 3



Additional wheel 4



Central console



Engine compartment



Documents



Interior arrangement



Registration Certificate



Towbar



Paint thickness Trunk



Paint thickness Roof



Paint thickness Door RL



Paint thickness Door RR



Paint thickness Door FL



Paint thickness Door FR



Paint thickness Bonnet




Paint thickness Wing RL




Paint thickness Wing RR



Paint thickness Wing FL



Paint thickness Wing FR




History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio

» Devaluation Damages


DEVALUATION FACTORS

1 - Seat cover FL - Stain - Cleaning



USAGE DAMAGES

1 - Windscreen - Stone chip(s) - Acceptable



2 - Bumper R - Scratch(es) - Acceptable

