



HYUNDAI IONIQ: 4574-LPB

Vinnumber:	KMHC751CGMU252591	Versionname:	1.6 GDI HEV Klass DCT berlina con portón 104kW 5P automática
First Registrationdate:	29/04/2021	Fiscalpower:	
Expertise Mileage:	192370	Power Kw:	
Bodytype:	Berline	Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Hybrid		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

195/65/15/91 H				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Registration document, Missing, Repair/replace (lump sum)



Door panel FL, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Door panel RR, Scratch(es), Replace



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Paint



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Unclassped, Dismount/Mount



Headlight R, Scratch(es), Polish



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Paint



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding RM, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check





