



OPEL CROSSLAND: GG-452-WY

Vinnumber:	W0V7H9EJ8N4188835	Versionname:	OPEL CROSSLAND 1.5 Diesel 120ch Auto Elegance Business VP [5P] bva 6-120CH-6cv (SUV)
First Registrationdate:	13/06/2022	Fiscalpower:	
Expertise Mileage:	70822	Power Kw:	88
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Seats electric F L	
GPS big screen color		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	
Steering wheel leather			Lining Other
Type of climate control	Autom climate control		Lining Semi-leather

Tyres

	195/60/16/93 H			
Summer tyres:	Fr.L.	Michelin: 15%	Fr.R.	Michelin: 15%
	Re.L.	Michelin: 15%	Re.R.	Michelin: 15%
Tyre profile depth FL				7.2
Tyre profile depth FR				7.2
Tyre profile depth RL				7.2
Tyre profile depth RR				7.2
Tyre size FL				195/60 R 16 93 H
Tyre size FR				195/60 R 16 93 H
Tyre size RL				195/60 R 16 93 H
Tyre size RR				195/60 R 16 93 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Chemical cleaning



Interior covering B pillar R, Scratch(es), Repair/replace (lump sum)



Centre console, Scratch(es), Acceptable



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Replace





Internal boot lining R, Scratch(es), Replace



Rear bulkhead lining, Scratch(es), Replace



Bumper spoiler Rear, Scratch(es), Replace



Historique Maintenance

Immatriculation: **GG-452-WY**

Date de 1ère immatriculation: **13/06/2022**

Modèle: **Opel CROSSLAND 1.5 Diesel 120ch Auto Elegance Business VP [5P] bva 6-120CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
13/03/2025	48.605	S.A DISTRIBUTION AUTOMOBILE COMPIEGNOISE	LIQUIDE DE FREIN
	0		PLAQUETTES AR RPLT
	0		DISQUES PLAQUETTES AV RPLT
27/09/2024	35.630	SAS AISNE OISE AUTOMOBILES	KLAXON RPLT
	0		DIAG
03/09/2024	32.914	KRYSTAL S.A.S	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		LIQUIDE DE FREIN
03/08/2023	17.600	LEGRAND AUTO 24	REVISION