

INSPECTION REPORT

End of contract

GENERAL INFO

File	314351
License plate	2CGW619
Vehicle identification number	WBA7K310007L42657
Dossier	2022017076
Make	BMW 118i 100kW Aut.
Mileage	38989
First registration	20/07/2022
client availability date	03/06/2026
inspectionDate	08/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
33	Front Bonnet // Repair & Painting	N
133	Bumper Rear // Painting	N
184	Wing Rear Right // Repair & Painting	N
191	Door Rear Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
223	Side View Mirror Right // Replace Not Painted	Y
225	Side View Mirror Right // Polish	Y
64	Wing Front Left // Repair & Painting	N
73	Side View Mirror Left // Replace Not Painted	Y
86	Door Front Left // Polish	Y
92	Rocker Panel Left // Painting	N
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
154	Rear Bonnet // Repair & Painting	Y
165	Roof // Polish	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	Y
346	Tyre Front Right // Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	N

Damage Pictures



Side View Mirror Right // Replace Not Painted-scratch



Side View Mirror Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Left // Painting-scratch



Door Front Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Front Left // Repair & Painting-scratch + dent




Side View Mirror Left // Replace Not Painted-scratch



Wheel Alloy Rear Left // Repair-scratch



Rocker Panel Left // Painting-scratch






Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch






Wing Rear Left // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction



Tyre Front Right // Replace-tear



Interior Cleaning // Large-stain



Rear Bonnet // Repair & Painting-scratch + dent




Bumper Front // Repair & Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Smart Repair Medium-scratch + dent





Bumper Rear // Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent