



BMW 1 Reeks (UKL): 2EDL957

Vinnumber:	WBA7M710407M79733	Versionname:	116d (F40) 1.5d 116pk/cv 5p
First Registrationdate:	6/09/2023	Fiscalpower:	
Expertise Mileage:	58692	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	6000.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/65/16/91 W			
Summer tyres:	Fr.L.	Michelin: 4,8 mm	Fr.R.	Michelin: 3,6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				4.8
Tyre profile depth FR				3.6
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/65 R 16 91 W
Tyre size FR				205/65 R 16 91 W
Tyre size RL				205/65 R 16 91 W
Tyre size RR				205/65 R 16 91 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Ignition key, Not functioning (well), Check



Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Spot repair



Alloy rim RL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror base L, Scratch(es), Acceptable



Door FL, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Dent(s), Paintless dent repair



Tyre repair kit, Missing, Check



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace



Door window RR, Scratch(es), Replace



Step R, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Door RR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Side window trim RR, Deformed / Strained, Replace



Bodywork, Paint measurement, Acceptable



Bodywork, Not original part, Remove lettering



Kenteken	2EDL957
Merk Model	BMW 116d (F40) 1.5d 116pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	9/6/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/16/26	56,069	BMW/MINI service standaard omvang	Uitvoeren
6/16/26	56,069	klein materiaal	
6/16/26	56,069	remblokken achter	Vervangen
6/16/26	56,069	remvloeistof	Vervangen
10/31/25	42,477	BMW/MINI service standaard omvang	Uitvoeren
10/31/25	42,477	BMW/MINI service voertuig-check	Uitvoeren
10/31/25	42,477	klein materiaal	
10/31/25	42,477	koelwatervloeistof	Bijvullen/-laden
10/31/25	42,477	service luchtfilter	Uitvoeren
10/31/25	42,477	service microfilter	Uitvoeren
10/31/25	42,477	service motorolie	Uitvoeren
12/5/24	21,092	batterij	Vervangen
12/5/24	21,092	BMW/MINI service standaard omvang	Uitvoeren
12/5/24	21,092	controle niveaus	Uitvoeren
12/5/24	21,092	klein materiaal	
12/5/24	21,092	service microfilter	Uitvoeren
12/5/24	21,092	service motorolie	Uitvoeren