



VOLKSWAGEN GOLF: GN-108-XA

Vinnumber:	WVWZZZCDXPW179882	Versionname:	VOLKSWAGEN GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)
First Registrationdate:	11/05/2023	Fiscalpower:	
Expertise Mileage:	58877	Power Kw:	81
Bodytype:	Berline	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Bridgestone: 30%	Fr.R.	Bridgestone: 30%
	Re.L.	Bridgestone: 30%	Re.R.	Bridgestone: 35%
Tyre profile depth FL	6.2			
Tyre profile depth FR	6.3			
Tyre profile depth RL	6.1			
Tyre profile depth RR	6.0			
Tyre size FL	205/55 R 16 91 V			
Tyre size FR	205/55 R 16 91 V			
Tyre size RL	205/55 R 16 91 V			
Tyre size RR	205/55 R 16 91 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Alloy rim FL, Scratch(es), Repair/replace (lump sum)			





Door FL, Scratch(es), Paint



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Boot lid covering R, Missing, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GN-108-XA** Date de 1ère immatriculation: **11/05/2023**

Modèle: **Volkswagen GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
09/04/2026	54.206	COURTOISE MOTORS ROISSY EN FRANCE	PLAQUETTES AR RPLT
	0		REVISION
	0		DISQUES PLAQUETTES AV RPLT
11/02/2026	53.360	COURTOISE MOTORS ROISSY EN FRANCE	BATTERIE RPLT
11/02/2026	53.360	COURTOISE MOTORS ROISSY EN FRANCE	ALTERNATEUR RPLT
11/02/2026	53.360	COURTOISE MOTORS ROISSY EN FRANCE	Frais de participation à l'environnement
03/03/2025	30.808	COURTOISE MOTORS	BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AR
24/04/2024	5.677	VELIZY AUTOMOBILES	RETROVISEUR D RPLT
	0		FEU AVD RPLT