



Expertise

Protocol number: 46199891  
Order No. / Reference: 26496528  
Inspection date: 29 Jun 2026

Manufacturer: Volkswagen

Model: Tiguan Allspace 2.0 TDI SCR DSG Life

VIN: WVGZZZ5NXRM023132



| Vehicle details                                 |                       |
|-------------------------------------------------|-----------------------|
| Manufacturer / Type / Model / Equipment         |                       |
| Volkswagen Tiguan Allspace 2.0 TDI SCR DSG Life |                       |
| Vehicle Identification number                   | WVGZZZ5NXRM023132     |
| Mileage (Read)                                  | 196,471 km            |
| First registration                              | 8 Feb 2024            |
| Number of holders                               | 1                     |
| Next periodical technical inspection            | 02/2027               |
| (Report not on hand)                            |                       |
| Power / Engine displacement                     | 110 kw / 1,968 ccm    |
| Fuel type / Cylinder                            | Diesel / 4            |
| Gearbox / Number of gears                       | Automatic / 7         |
| Type of drive                                   | Front drive           |
| Type of vehicle                                 | SUV                   |
| Colour / colour code                            | Deep Black Perleffekt |
| Doors / Seats                                   | 5 / 5                 |
| Upholstery type                                 | Cloth                 |
| Colour of upholstery                            | Black-Anthracite      |
| Re-import                                       | no                    |
| Vehicle with smoke odor                         | no                    |
| readiness to drive                              | Roadworthy            |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 25,200 km                                                  |
| <b>Last service on / at</b>                      | 05/2026 at 191,642 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GY267343                                                   |
| <b>Previous damage / Accident</b>                | None detectable              | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                   |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 0603 / BZG 31819             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,270 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R18 100V | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |
| 2) | 235/55 R18 100V | Summer tyres on Light alloy | Continental  | 6mm / 6mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                               | Manufacturer | Tread depth |
|----|----------------|--------------------------------------------|--------------|-------------|
| 1) | 215/65 R17 99H | Winter tyres on Steel rim with wheel cover | Continental  | 5mm / 5mm   |
| 2) | 215/65 R17 99H | Winter tyres on Steel rim with wheel cover | Continental  | 5mm / 5mm   |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment



## Standard equipment

- Storage compartments in the overhead console
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Adaptive Cruise Control (ACC) "stop & go" with speed limiter
- third brake light
- Silver anodized roof rails
- Diesel particulate filter
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- Electronic parking brake including auto-hold function
- Automatic headlight control with LED daytime running lights, "Coming home" and "Leaving home" function
- High beam control Light Assist
- Pedestrian detection
- Luggage compartment lighting - additional, removable and usable as a flashlight
- Glove compartment with cooling option
- Rear window heated
- Rear window wiper with intermittent function
- ISOFIX mounting points for attaching 2 child seats to the rear seats - also for i-Size child seats
- Rear headrests (3)
- LED reading lights, 2 in the front and 2 in the rear
- LED headlights
- Light in the front footwell
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Emergency call service - no registration required, service is activated upon delivery
- Radio accessories: 8 speakers
- Rain sensor
- Wheels: AirStop tires 235/55 R 18, optimized for low rolling resistance
- Gearshift knob in leather
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts with belt tensioners for the outer rear seats
- Seats: Comfort seats in the front
- Seats: Lumbar support in the front
- Lane keeping assistant "Lane Assist"
- 12-volt power outlet on the rear center console and in the luggage compartment
- Bumpers in body color - lower bumper sections black
- Textile floor mats front and rear
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys
- Airbag for driver and front passenger including knee airbag on the driver's side - front passenger airbag deactivation - knee airbag on the driver's side
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings painted silver
- Chrome trim on the side windows
- Decorative inserts "Horizont Black" - for instrument panel and front door trim
- Parking aid - acoustic warning signals for obstacles in the front and rear area
- Electronic stability program with counter-steering support including ABS, ASR, EDS, MSR and trailer stabilization
- Electric windows front and rear
- Windscreen made of laminated safety glass, heat and sound insulating
- Luggage compartment floor height adjustable in 2 stages
- Transmission: 7-speed DSG
- Tailgate with electric opening and closing, adjustable opening angle
- Interior mirror automatically dimming
- Air conditioning "Air Care Climatronic" - 3-zone temperature control - allergen filter - rear controls
- Front headrests - safety-optimized - longitudinally and height-adjustable
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Armrest - centre, rear
- Non-smoking version - storage compartment and 12V socket at the front
- Proactive occupant protection system in conjunction with "Front Assist"
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Tire Mobility Set omitted
- Wheels: Light alloy (4) "Frankfurt" 7 J x 18 - Tires 235/55 R 18
- Electromechanical power steering - speed-dependent control
- Seats: Front passenger seat backrest folds down completely
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Power outlet: 2 USB-C ports on the front, charging power up to 45 W
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear



### Extra equipment

- Anti-theft alarm system with safe locking - Anti-theft alarm system with interior monitoring, - Backup horn and tow-away protection - Central locking with safe locking, - Remote control and 2 remote folding keys
- App-Connect Wireless for Apple CarPlay and Android Auto
- Mesh partition
- Navigation system "Discover Pro" incl. "Streaming & Internet" - 8 speakers - App-Connect Wireless for Apple CarPlay and Android Auto - Digital radio reception DAB+ - Navigation system "Discover Pro" incl. "Streaming & Internet" - Radio - Voice control - Traffic sign recognition
- Package: Business Premium incl. Navigation (DSG) - 2 USB-C ports in the front, 1 USB-C charging port on the rear center console - Leather multifunction steering wheel, heated, with paddle shifters - Automatically heated windshield washer nozzles - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats
- Paint finish: Pearl effect
- Rear View reversing camera
- Seats: ergoActive front seats - front passenger seat backrest not foldable - ergoActive front seats height-adjustable, seat and backrest tilt adjustable, thigh support longitudinally adjustable - lumbar support in front electrically adjustable with massage function - seat center panels of the front seats and outer rear seats in microfleece "ArtVelours" - top comfort seats in front
- Surround view "Area View" including reversing camera "Rear View"
- "Comfort" telephone interface with inductive charging function - operation and display via the multifunction display and touchscreen of the radio or radio navigation system as well as via the multifunction steering wheel - hands-free system - Bluetooth audio - external antenna connection with LTE support - 2 USB interfaces, also for iPod/iPhone; 1 USB charging socket and multimedia socket AUX-IN
- 230 volt socket
- Electrically adjustable, folding and heated exterior mirrors - with passenger-side mirror lowering function
- Package: "Easy Open & Close" with safe locking mechanism - "Easy Open & Close" - tailgate with sensor-controlled opening and closing, with remote unlocking - Keyless locking and starting system "Keyless Access" with safe locking mechanism
- Package: Winter additionally includes heated outer rear seats - "Air Care Climatronic" air conditioning with active combination filter, rear controls and 3-zone temperature control - automatically heated front windshield washer nozzles - heated front seats and outer rear seats
- Park Assist system including parking aid
- Power outlets: 2 USB-C ports at the front, 1 USB-C charging port at the rear of the center console. Charging power up to 45 W.
- Seats: Heated front seats
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters, heated
- Voice control
- Windows: Rear side windows and rear window tinted

### Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                        |



## Value reducing factors

| No. | Component group        | Description                                                           |
|-----|------------------------|-----------------------------------------------------------------------|
| 1   | Door - front left side | Door edge - Scratch(es) - Smart repair                                |
| 2   | Trim / covers          | Boot lid - interior trim - Scratched - Loss in value                  |
| 3   | Interior               | Cargo area floor - Deformed - Replace                                 |
| 4   | Vehicle glazing        | Windscreen with lane departure assistant - Stone chips - Smart repair |
| 5   | Boot lid / rear door   | Boot lid glazed - dent(s) - Smart repair                              |
| 6   | Trim / covers          | D-pillar - trim - interior, right side - Scratched - Replace          |
| 7   | Trim / covers          | D-pillar trim - interior, left side - Scratched - Replace             |
| 8   | Front bumper           | Front bumper - Scratch(es) - Paint                                    |
| 9   | Electronic systems     | Front camera - Broken / torn - Replace                                |
| 10  | Bonnet                 | Bonnet - Stone chips - Paint                                          |
| 11  | Rear bumper            | Bumper with Parktronic (Unterteil) - Deformed - Replace               |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

ALPHABET



**Figure 1:** Diagonal front (left)

ALPHABET



**Figure 2:** Diagonal front (right)

ALPHABET




**Figure 3:** Diagonal rear (left)

ALPHABET



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




**Damage 1:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 2:** Trim / covers: Boot lid - interior trim - Scratched - Loss in value



**Damage 2:** Trim / covers: Boot lid - interior trim - Scratched - Loss in value



**Damage 2:** Trim / covers: Boot lid - interior trim - Scratched - Loss in value



**Damage 2:** Trim / covers: Boot lid - interior trim - Scratched - Loss in value



**Damage 3:** Interior: Cargo area floor - Deformed - Replace




**Damage 3:** Interior: Cargo area floor - Deformed - Replace



**Damage 3:** Interior: Cargo area floor - Deformed - Replace




**Damage 4:** Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Smart repair




**Damage 4:** Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Smart repair



**Damage 5:** Boot lid / rear door: Boot lid glazed - dent(s) - Smart repair



**Damage 5:** Boot lid / rear door: Boot lid glazed - dent(s) - Smart repair



**Damage 5:** Boot lid / rear door: Boot lid glazed - dent(s) - Smart repair



**Damage 6:** Trim / covers: D-pillar - trim - interior, right side - Scratched - Replace



**Damage 6:** Trim / covers: D-pillar - trim - interior, right side - Scratched - Replace



**Damage 7:** Trim / covers: D-pillar trim - interior, left side - Scratched - Replace




**Damage 7:** Trim / covers: D-pillar trim - interior, left side - Scratched - Replace



**Damage 8:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 8:** Front bumper: Front bumper - Scratch(es) - Paint




**Damage 8:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 9:** Electronic systems: Front camera - Broken / torn - Replace



**Damage 9:** Electronic systems: Front camera - Broken / torn - Replace



**Damage 9:** Electronic systems: Front camera - Broken / torn - Replace



**Damage 10:** Bonnet: Bonnet - Stone chips - Paint



**Damage 10:** Bonnet: Bonnet - Stone chips - Paint



**Damage 10:** Bonnet: Bonnet - Stone chips - Paint




**Damage 10:** Bonnet: Bonnet - Stone chips - Paint



**Damage 11:** Rear bumper: Bumper with Parktronic (Unterteil) - Deformed  
- Replace



**Damage 11:** Rear bumper: Bumper with Parktronic (Unterteil) - Deformed  
- Replace



**Damage 11:** Rear bumper: Bumper with Parktronic (Unterteil) - Deformed  
- Replace



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZ5NXRM023132

Hersteller / Modell: VOLKSWAGEN VW Tiguan Allspace 2.0 TDI SCR DSG Life

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 12.05.2026 | 191.642  | Bremse Sonstiges; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 28.01.2026 | 160.687  | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| 22.12.2025 | 152.157  | Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 07.11.2025 | 136.128  | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 13.08.2025 | 110.562  | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Getriebeöl ern/ prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 09.04.2025 | 82.080   | Bremse Sonstiges; Bremse Sonstiges; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze hinten; Bremsklötze hinten; Bremsklötze vorne; Bremsklötze vorne; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben hinten; Bremsscheiben hinten; Bremsscheiben vorne; Bremsscheiben vorne; Bremsscheiben vorne; Kraftstofffilter ern; Kraftstofffilter ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Luftfiltereinsatz ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Motoröl b. Wartung; Motoröl b. Wartung; Ölfilter ern; Ölfilter ern; Ölfilter ern; Regelwartungsdienst; Regelwartungsdienst; Regelwartungsdienst; Systemtest/Eigendiagnose; Systemtest/Eigendiagnose; Systemtest/Eigendiagnose; Wartung Sonstiges; Wartung Sonstiges; Wartung Sonstiges |
| 06.12.2024 | 53.625   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 22.10.2024 | 29.125   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 09.10.2024 | 39.912   | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |