MACADAM










PEUGEOT E-208: GQ-620-WA

Vinnumber:	**VR3UHZKXZPT634912**	Versionname:	**PEUGEOT E-208 Electrique 156ch GT VP [5P] bva 1-156CH-4cv (bi-corps)**
First Registrationdate:	**24/08/2023**	Fiscalpower:	
Expertise Mileage:	**24363**	Power Kw:	**115**
Bodytype:	**Berline**	Body colour	**Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Electric**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	**HD**	Headlight sprinkler	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	**Lining Semi-leather**
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/45/17/88 H**			
	Fr.L.	**Michelin: 55%**	Fr.R.	**Michelin: 40%**
	Re.L.	**Michelin: 40%**	Re.R.	**Michelin: 40%**

Tyre profile depth FL	**4.7**
Tyre profile depth FR	**5.5**
Tyre profile depth RL	**5.5**
Tyre profile depth RR	**5.7**
Tyre size FL	**205/45 R 17 88 H**
Tyre size FR	**205/45 R 17 88 H**
Tyre size RL	**205/45 R 17 88 H**
Tyre size RR	**205/45 R 17 88 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Alloy rim RR bitone/polychrome, Scratch(es), Acceptable






Alloy rim FR bitone/polychrome, Scratch(es), Acceptable





Door FL, Scratch(es), Paint




Bumper F, Scratch(es), Paint





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)







Wing trim RR, Scratch(es), Paint




Door RR, Dent(s) and scratch(es), Acceptable





Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Polish




Bumper moulding R, Scratch(es), Polish




ALPHABET

Historique Maintenance

Immatriculation: **GQ-620-WA** Date de 1ère immatriculation: **24/08/2023**

Modèle: **Peugeot E-208 Electrique 156ch GT VP [5P] bva 1-156CH-4cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
23/12/2024	11.381	ETS FAHY	BALAIS ESSUIE GLACE AV
			REVISION
			BALAI ESSUIE GLACE AR
25/08/2026	10.741	FLEET SOLUTIONS FRANCE	Rotation des pneus
			DIVERS PNEUS
			DIVERS PNEUS
			DIVERS PNEUS
			DIVERS PNEUS
			Rotation des pneus
			Rotation des pneus
			Rotation des pneus
04/12/2024	8.256	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER