



Expertise

Protocol number: 46514092
Order No. / Reference: 26662135
Inspection date: 1 Jul 2026

Manufacturer: Volkswagen
VIN: WVVZZZCDZNW193444

Model: Golf Life 2.0 TDI SCR DSG Active



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Golf Life 2.0 TDI SCR DSG Active	
Vehicle Identification number	WVVZZZCDZNW193444
Mileage (Read)	125,566 km
First registration	2 Jun 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Deep Black Perleffekt (C9X)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	29,700 km
Last service on / at	06/2026 at 125,256 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ187107
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CNX 01131		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,950 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Nexen	3mm / 3mm
2)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Nexen	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91W	Summer tyres on Light alloy	Nexen	5mm / 5mm
2)	225/45 R17 91W	Summer tyres on Light alloy	Nexen	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 02/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 2 USB-C ports on the front
- Turning brake function and evasive steering support (When making left turns, the Golf with the turning assistant automatically brakes to a standstill (with a simultaneous acoustic and visual warning) should a vehicle approach in the lane to be crossed. Depending on the speed of both vehicles, the turning assistant can, within the system limits, prevent the accident or mitigate its consequences.)
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto (selected apps for Android smartphones and Apple iPhones can be displayed and operated on the touchscreen of the radio or navigation system)
- Vehicle tool kit
- Car2X (Using the WLANp ITS G5 standard, all Car2X-enabled vehicles and traffic systems such as traffic lights can transmit data at high speed without using the mobile network. This works over a distance of around 800 meters - enough to warn of an invisible traffic jam.)
- Parking aid (acoustic warning signals for obstacles in the front and rear area)
- Electronic stability program and electromechanical brake booster (Anti-lock braking system with brake assist - Electronic brake force distribution - Traction control - Electronic differential lock - Engine drag torque control - Trailer stabilization)
- Electric windows, front and rear
- Windscreen made of laminated safety glass, heat and sound insulating
- Pedestrian protection measures expanded
- Transmission: 7-speed DSG (7-speed dual-clutch transmission DSG)
- Rear spoiler
- Air conditioning system "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- LED reading lights at the front (2) and 2 at the rear
- LED taillights
- Steering wheel: Multifunction leather steering wheel, heated, with paddle shifters
- Front center armrest adjustable in height and length
- Navigation system "Discover Media" incl. "Streaming & Internet" (6+1 speakers - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Multifunction camera - Navigation system "Discover Media" incl. "Streaming & Internet" - Radio - Traffic sign recognition)
- Emergency call service (no registration required, service is activated upon delivery)
- Package: Light and Sight Package incl. High Beam Control "Light Assist" (High Beam Control "Light Assist" - Automatically Dimming Interior Mirror - Multifunction Camera - Rain Sensor)
- Brushed stainless steel pedals
- Radio accessories: Digital radio reception DAB+
- Wheels: Alloy wheels (4) "Galway" 7 J x 16 in black, polished surface (tires 205/55 R 16)
- 2 USB charging ports on the rear of the center console
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Ambient lighting 30-color (LED light in the front footwell, light color selectable)
- Extended warranty, 3 years following the manufacturer's warranty, maximum total mileage 50,000 km
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- Exterior mirror housings and door handles in body color
- third brake light
- Pearl grey headliner
- Decorative inlays for special model
- Diesel particulate filter and SCR catalyst
- Digital Cockpit Pro, multicolor (various info profiles selectable)
- Electronic differential lock XDS
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights (as well as welcome and farewell lights)
- Driving profile selection (possibility to set different vehicle settings: Comfort, Normal, Sport, Eco, Individual - adaptable vehicle systems include: engine, adaptive chassis control DCC, DSG, steering, start-stop system, cornering lights and "Dynamic Light Assist", automatic distance control ACC, air conditioning)
- luggage compartment cover
- Rear window heated
- Rear window wiper with intermittent function
- ISOFIX mounting points (for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Rear headrests (3)
- Front headrests (safety-optimized)
- LED light in the front footwell, selectable light color
- LED headlights
- Dynamic headlight range control
- Illuminated makeup mirrors in the sun visors
- Fatigue detection (detects signs of possible driver fatigue based on characteristic steering behavior, time of day and driving duration and issues a visual and audible warning)
- Non-smoking version (storage compartment and 12V socket at the front)
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection (detects critical distance situations to other vehicles and helps to shorten the stopping distance - warns the driver visually and audibly in dangerous situations as well as with a preventive braking jolt with pedestrian and cyclist detection - also reacts to pedestrians and cyclists)
- Radio accessories: 6 + 1 speakers
- Tire pressure monitoring system (passive)



- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Rear side windows and rear window tinted
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Comfort seats in the front
- Seats: Heated front seats
- Voice control
- Start-stop system (with brake energy recuperation)
- Bumpers in body color
- Textile floor mats front and rear
- Ambient lighting with logo projection
- Traffic sign recognition
- Warning tone and light for unfastened seat belts front and rear

- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Heated windshield washer nozzles, front
- Keyless start system without safe locking
- Electromechanical power steering (speed-dependent control)
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers for special model
- Seats: Lumbar support in the front
- Seats: Front seats are height-adjustable
- Lane keeping assistant "Lane Assist"
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Illuminated door handle recesses
- First aid kit, warning triangle and high-visibility vest
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote folding keys

Extra equipment

- Towbar, foldable with electric release
- Adaptive Cruise Control ACC "stop & go" (Adaptive Cruise Control ACC incl. speed limiter - Emergency braking assistant "Front Assist" with pedestrian and cyclist detection)
- Paint finish: Pearl effect
- LED Plus headlights
- Package: "Plus" package for special models (4 "Ventura" 7.5 J x 17 alloy wheels - black exterior mirror housings - illuminated strip between the headlights and door handle recesses - wheel locks with enhanced anti-theft protection - 225/45 R 17 tires - "Comfort" telephone interface with inductive charging function - preparation for mobile key, for vehicle access via smartphone)
- Wheels: Winter wheels (additional) steel, 6.5 J x 16 (4 steel wheels 6.5 J x 16 - wheel wrench and jack - winter tires 205/55 R16 H)
- "Comfort" telephone interface with inductive charging function (hands-free system)
- Extended warranty: Cancelled
- Chassis: Sport chassis (the driver can choose between two different chassis settings - the "Normal" setting allows for dynamic driving behavior without sacrificing a comfortable driving experience; the "Sport" setting further stiffens the damping and enables an even more dynamic driving feel)
- Progressive steering (the steering ratio is progressively increased with increasing steering angle - the steering behavior becomes noticeably more direct depending on the driving situation, the steering wheel movements are significantly reduced and thus steering comfort is increased)
- Wheels: Alloy wheels (4) "Ventura" 7.5 J x 17 (wheel locks with enhanced theft protection - tires 225/45 R 17)
- Rear View reversing camera
- Seats: Front passenger seat backrest folds down completely

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.



Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Mudguard - right side	Mudguard - right side - Scratch(es) - Smart repair
3	Sill - left side	Sill - Scratch(es) - Smart repair
4	Front bumper	Front bumper - Scratch(es) - Smart repair
5	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
6	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
7	Wing mirror - left side	Cap - Scratch(es) - Paint
8	Wing mirror - right side	Cap - Scratch(es) - Paint
9	Wheel / tyres	Tyre - front (3mm) - does not meet manufacturer specifications - Replace
10	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
11	Door - front right side	Door - Scratch(es) - Paint
12	Rear bumper	Rear bumper - Scratch(es) - Paint
13	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
14	Vehicle glazing	Windscreen - Stone chips - Replace

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.





Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 2: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair




Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 7: Wing mirror - left side: Cap - Scratch(es) - Paint



Damage 7: Wing mirror - left side: Cap - Scratch(es) - Paint




Damage 8: Wing mirror - right side: Cap - Scratch(es) - Paint




Damage 8: Wing mirror - right side: Cap - Scratch(es) - Paint



Damage 9: Wheel / tyres: Tyre - front (3mm) - does not meet manufacturer specifications - Replace



Damage 9: Wheel / tyres: Tyre - front (3mm) - does not meet manufacturer specifications - Replace




Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - front right side: Door - Scratch(es) - Paint




Damage 11: Door - front right side: Door - Scratch(es) - Paint




Damage 11: Door - front right side: Door - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 13: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 13: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 13: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 13: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 13: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 14: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 14: Vehicle glazing: Windscreen - Stone chips - Replace