MACADAM











BMW 1 Reeks (UKL): 2CQK472

Vinnumber:	**WBA7M710805V91804**	Versionname:	**116d (F40) 1.5d 116pk/cv 5p**
First Registrationdate:	**18/10/2022**	Fiscalpower:	
Expertise Mileage:	**81844**	Power Kw:	**85**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**01/10/2027**		
Maintenance	**4900.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 W**			
	Fr.L.	**Michelin: 5 mm**	Fr.R.	**Michelin: 5 mm**
	Re.L.	**Michelin: 6 mm**	Re.R.	**Michelin: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**205/55 R 16 91 W**
Tyre size FR	**205/55 R 16 91 W**
Tyre size RL	**205/55 R 16 91 W**
Tyre size RR	**205/55 R 16 91 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Seat cover FL, Worn, Acceptable







Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Mirror side repeater L, Broken, Replace



Outside rear-view mirror base L, Broken, Replace



Tailgate / Boot, Scratch(es), Spot repair



Door RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Bodywork, Dirty, Check



Onderhoudshistorie van: WBA7M710805V91804

ALPHABET

Kenteken	2CQK472
Merk Model	BMW 116d (F40) 1.5d 116pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	10/18/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/27/26	73,678	BMW/MINI service standaard omvang	Uitvoeren
7/27/26	73,678	controle niveaus	Uitvoeren
7/27/26	73,678	klein materiaal	
7/27/26	73,678	koelwatervloeistof	Bijvullen/-laden
7/27/26	73,678	remblokken vooraan	Vervangen
7/27/26	73,678	ruitenwisservloeistof	Bijvullen/-laden
4/23/26	67,660	druksensor diesel partikelfilter/DPF	Vervangen
4/23/26	67,660	klein materiaal	
4/23/26	67,660	NOx sensor	Vervangen
2/3/26	63,817	batterij	Vervangen
2/3/26	63,817	BMW/MINI service standaard omvang	Uitvoeren
2/3/26	63,817	BMW/MINI service voertuig-check	Uitvoeren
2/3/26	63,817	BMW/MINI voertuigcontrole	Uitvoeren
2/3/26	63,817	klein materiaal	
2/3/26	63,817	service luchtfilter	Uitvoeren
2/3/26	63,817	service microfilter	Uitvoeren
2/3/26	63,817	service motorolie	Uitvoeren
9/30/25	57,449	BMW/MINI service standaard omvang	Uitvoeren
9/30/25	57,449	remvloeistof	Vervangen
7/10/25	52,294	BMW/MINI service standaard omvang	Uitvoeren
7/10/25	52,294	klein materiaal	
7/10/25	52,294	remblokken achter	Vervangen
11/6/24	35,761	BMW/MINI service standaard omvang	Uitvoeren
11/6/24	35,761	klein materiaal	
11/6/24	35,761	service microfilter	Uitvoeren
11/6/24	35,761	service motorolie	Uitvoeren