

Volkswagen

VIN: WV1ZZZSK1RX057253

Estimated repair cost

333.00 EUR
TOTAL



Description

Registration number 2HBA858	Registration date -	Odometer 28425 km
Color -	Year -	Upholstery -
Number of doors -	Number of seats -	Generation -

Vehicle Equipments

Rear-view camera	Heated door mirrors	Park Assist
Cruise control	Manual air-conditioning	

Statement details

Inspection loc PARC GENERAL LEASE	Statement date 04/02/2026	Inspection approval date 05/02/2026
---------------------------------------------	-------------------------------------	-----------------------------------------------

Control

Engine start issue No	Is not roadworthy No
---------------------------------	--------------------------------

Defects & corrections

#	Element	Defect	Correction	net cost
001	Bumper / Back ¹ Painted : Yes	Scratched	Repair	193.00 EUR

	Bodywork time	Paint time	Part Price	Lumpsum
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	-
	-	193.00 EUR	-	
002	Exterior complete / -	Sticker	Cleaning	100.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	100.00 EUR
	-	-	-	
003	Door / Right ²	Dent	Smart repair	40.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	40.00 EUR
	-	-	-	

¹ Ovb, deuken

² X2

Loose Items

- | | | |
|-----------------------------------------------------|---------------------------------------------------|--------------------------------------------------------------|
| <input type="checkbox"/> Rear parcel shelf | <input type="checkbox"/> Remote key | <input checked="" type="checkbox"/> Tyre repair kit complete |
| <input type="checkbox"/> Security Kit | <input type="checkbox"/> Cabrio wind deflector | <input type="checkbox"/> Cabrio wind deflector bag |
| <input type="checkbox"/> Compressor tyre repair kit | <input type="checkbox"/> Document holder | <input checked="" type="checkbox"/> Triangle |
| <input type="checkbox"/> DVD screen | <input checked="" type="checkbox"/> First aid kit | <input type="checkbox"/> Warranty booklet |
| <input type="checkbox"/> User manual | <input type="checkbox"/> Memory card | <input type="checkbox"/> Toolkit |
| <input type="checkbox"/> Fragrance diffuser | <input type="checkbox"/> Hook /Hicth ball | <input type="checkbox"/> Jack |
| <input type="checkbox"/> Jack handle crank | <input type="checkbox"/> Card key | <input type="checkbox"/> Load cover |
| <input type="checkbox"/> Slow charging cable | <input type="checkbox"/> Mechanical key | <input type="checkbox"/> Refill tyre repair kit |
| <input type="checkbox"/> Charging cable bag | <input type="checkbox"/> Conformity certificate | <input checked="" type="checkbox"/> Spare Key |
| <input type="checkbox"/> Spare wheel tyre | <input type="checkbox"/> Separation net | <input type="checkbox"/> Service book |
| <input type="checkbox"/> Quick charging cable | <input type="checkbox"/> In-car tools | <input type="checkbox"/> Towing hook |
| <input checked="" type="checkbox"/> Safety vest | <input type="checkbox"/> Divider bar of the bag | <input type="checkbox"/> Locking wheel nut |
| <input type="checkbox"/> Cargo net | | |

Main set of tyres

Front Left	CONTINENTAL	205 / 60 / 16 / Winter	6 mm
Front Right	CONTINENTAL	205 / 60 / 16 / Winter	6 mm
Back Left	BRIDGESTONE	205 / 60 / 16 / All	4 mm
Back Right	BRIDGESTONE	205 / 60 / 16 / All	4 mm

Comments

Ovb, wagen vochtig (Nat)

Pictures



Front left




Rear left



Boot opened




Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation




Spare Tyre




Vin



Other



Other



Other



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Exterior complete / - / Sticker



Exterior complete / - / Sticker



Exterior complete / - / Sticker




Exterior complete / - / Sticker



Exterior complete / - / Sticker



Door / Right / Dent



Door / Right / Dent

