

INSPECTION REPORT

End of contract

GENERAL INFO

File	309766
License plate	2BQM127
Vehicle identification number	WMW31BB0002S27158
Dossier	2021 194 021
Make	Mini Mini Clubm.One D 116 Aut.
Mileage	85350
First registration	15/02/2022
client availability date	02/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
33	Front Bonnet // Repair & Painting	N
86	Door Front Left // Polish	Y
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	N
162	Roof // Painting	N
184	Wing Rear Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	N
321	Wheel Alloy Rear Left // Repair	N

Damage Pictures



Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Door Front Left // Polish-scratch



Front Bonnet // Repair & Painting-scratch + dent




Wing Rear Left // Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent





Roof // Painting-Chemical reaction