
APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	AUDI
Model / version:	A1 SPORTBACK
Vin:	WAUZZZGB5RR020839
Plate:	2ENL833
Mileage:	43066
First registration:	30/11/2023
Color:	MYTHOS BLACK


ADDITIONAL INFORMATION



Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





















VIN INFORMATION

Boîte manuelle	5 rapports	Becquet arrière
Matière : tôle	Lettre repère (J)	Diamètre avant 15
Diamètre arrière 15	Largeur avant 5,5	Largeur arrière 5,5
Diamètre avant 15	Diamètre arrière 15	Hauteur avant 65
Hauteur arrière 65	Indice de vitesse avant V	Indice de vitesse arrière V
Largeur avant 185	Largeur arrière 185	Climatisation
Climatisation réfrigérant 1234YF	Alternateur 140 Ampères	Euro 6
Métallisée vernissée	Freins avant à disques	Rétroviseur gauche à réglage électrique
Rétroviseur droit à réglage électrique	Rétroviseur gauche chauffant	Rétroviseur droit chauffant
Siège avant gauche réglable en hauteur	Sièges avant réglable en hauteur	Fixations Isofix siège passager avant
Garnitures tissu	Volant cuir	Volant sport
Volant multifonction	Caméra avant	Régulateur automatique de la distance
Affichage lecture des panneaux de signalisation	Verrouillage centralisé à commande à distance	Airbag passager
Airbag passager désactivable	Freinage d'urgence assistée autonome (urbain)	depuis 10.23
radio avec récepteur numérique	999 cc (1,0 L) 70 KW	réservoir à charbon actif
barre stabilisatrice av 20,7x2,8 mm	encarts décoratifs look verre noir	

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓

Front seats heated:		Steering wheel:	
Electric windows:		Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:		Fast charging cables:	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		
Front right	5 mm			Summer		
Rear left	5 mm			Summer		
Rear right	5 mm			Summer		

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper R	Scratch(es)
2	Door RR	Dent(s) and scratch(es)

Total: 2

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS


1 - Bumper R - Scratch(es)



2 - Door RR - Dent(s) and scratch(es)



3 - Bodywork - Scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

30/07/2026 09:38