

2-DNH-970


2-DNH-970 · MY22 Mild-Hybrid 140 MT 2WD Tekna + Design Pack · 15 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DNH-970	Fuel Type	Hybrid Gasoline
Manufacturer	NISSAN	VIN	SJNTAAJ12U1192670
Model	Qashqai	Cylinder Capacity	1.332 ^{cm³}
Model Versions	MY22 Mild-Hybrid 140 MT 2WD Tekna + Design Pack	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	04-05-2023
Color	Blue	Odometer	86.652 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	103	Number Headrests	5

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable driver's seat
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel Navigation system
Bluetooth car kit	Panorama roof Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Steering wheel multifunction
Cruise control	
Electric rear windows	

Condition

Condition exterior Adequate

Last Maintenance Unknown

Condition interior Adequate

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Continental	235 ^{mm}	50 ^{mm}	19 ^{inch}	Summer
Rear Left	5 ^{mm}	Continental	235 ^{mm}	50 ^{mm}	19 ^{inch}	Summer
Front Right	2 ^{mm}	Continental	235 ^{mm}	50 ^{mm}	19 ^{inch}	Summer
Rear Right	5 ^{mm}	Continental	235 ^{mm}	50 ^{mm}	19 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Skirt - Left



Damage Type

Scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No




Damage Part

Reardoor - Left



Damage Type

Small scratch(es)



Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Frontdoor - Left



Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Hood



Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Alloy - Right Front



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Alloy - Right Rear



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part
Bumper - Rear



Damage Type
Scratch(es)




Repair Type
Spray

Acceptable
No



Damage Part
Tailgate



Damage Type
Damaged



Repair Type
Touch-up / Polish

Acceptable
No