MACADAM










Volkswagen ID.4: N711JL

Vinnumber:	**WVGZZZE2ZMP042830**	Versionname:	**ID 4 109kW / 52kWh Style Automaat**
First Registrationdate:	**28/10/2021**	Fiscalpower:	
Expertise Mileage:	**72125**	Power Kw:	**109**
Bodytype:		Body colour	**Mangan Grey metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**374**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Lining Alcantara	
Autom climate control		Rear parking sensors	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 60 / 18 / 107 / H / Aluminium	6,6 mm	Goodyear	Winter
	Right	235 / 60 / 18 / 107 / H / Aluminium	6,8 mm	Goodyear	Winter
Rear	Left	235 / 60 / 18 / 107 / H / Aluminium	5,6 mm	Goodyear	Winter
	Right	235 / 60 / 18 / 107 / H / Aluminium	4,8 mm	Goodyear	Winter

Assistance equipment

Number of charging cables (rapid charge)	**1**

Dashboard, Scratch(es), Smart repair




Door FL, Bad repair, Repair and paint (complete)





Door RL, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)










Door FR, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)






Wing FR, Dent(s) and scratch(es), Repair and paint (complete)






Wing RR, Dent(s) and scratch(es), Repair and paint (complete)







Roof pillar R, Scratch(es), Polish




Boot lid covering R, Scratch(es), Replace




Bumper R, Scratch(es), Smart repair





Tailgate / Boot, Scratch(es), Repair and paint (complete)




Roof, Scratch(es), Repair and paint (complete)






Onderhoudshistorie van: WVGZZZE2ZMP042830

ALPHABET

Kenteken	N711JL
Merk Model	Volkswagen ID 4 109kW / 52kWh Style Automaat
Brandstofsoort	Elektrisch
Datum deel1	10/28/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/3/26	68,598	Airco CO2 vulling
8/3/26	68,598	Onderhoudsbeurt
8/3/26	68,598	Remvloeistof
8/3/26	68,598	Ruitenwisserblad(en) achterzijde
8/3/26	68,598	Ruitenwisserblad(en) voorzijde
2/2/26	62,836	Airco pomp
10/23/25	56,217	APK
9/9/24	40,441	Reparatie band(en)
1/23/24	30,905	Ruitenwisserblad(en) voorzijde
6/26/23	22,278	Airco controle
6/26/23	22,278	Airco reinigen
8/19/22	9,850	Airco pomp
8/19/22	9,850	Ruitenwisserblad(en) achterzijde
8/19/22	9,850	Ruitenwisserblad(en) voorzijde