



BMW X1 (UKL): 2CDB308

Vinnumber:	WBA71AC0805V37616	Versionname:	X1 (F48) 18d sDrive 2.0d 136pk/cv 5p
First Registrationdate:	10/06/2022	Fiscalpower:	
Expertise Mileage:	150668	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	NOT OK		
Maintenance	30/06/2026		
Maintenance	-700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/97 W				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 5,4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.4
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 97 W
Tyre size FR				225/55 R 17 97 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
MOT certificate, Non-conforme, Replace			





Instrument panel, complete, Not functioning (well), Check



Door panel RR, Scratch(es), Smart repair



Seat cover FR, Worn, Acceptable



Bonnet, Stone chip(s), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Replace



Door RR, Dent(s) and scratch(es), Acceptable





Door FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Acceptable



Kenteken	2CDB308
Merk Model	BMW X1 (F48) 18d sDrive 2.0d 136pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	6/10/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/7/26	140,294	BMW/MINI service standaard omvang	Uitvoeren
4/7/26	140,294	klein materiaal	
4/7/26	140,294	remschijven en blokken achter	Vervangen
1/26/26	131,383	druksensor diesel partikelfilter/DPF	Vervangen
1/26/26	131,383	halogeenlamp	Vervangen
1/26/26	131,383	klein materiaal	
11/17/25	124,905	BMW/MINI service standaard omvang	Uitvoeren
11/17/25	124,905	klein materiaal	
11/17/25	124,905	service microfilter	Uitvoeren
11/17/25	124,905	service motorolie	Uitvoeren
10/1/25	118,149	controle niveaus	Uitvoeren
10/1/25	118,149	remschijven en blokken vooraan	Vervangen
3/7/25	95,219	BMW/MINI voertuigcontrole	Uitvoeren
3/7/25	95,219	service luchtfilter	Uitvoeren
3/7/25	95,219	service microfilter	Uitvoeren
3/7/25	95,219	service motorolie	Uitvoeren
12/27/24	90,561	halogeenlamp	Vervangen
12/27/24	90,561	remblokken achter	Vervangen
8/6/24	74,469	ruitenwisserrubber achter	Vervangen
8/6/24	74,469	service brandstoffilter	Uitvoeren
8/6/24	74,469	service microfilter	Uitvoeren
8/6/24	74,469	service motorolie	Uitvoeren
2/13/24	58,670	halogeenlamp	Vervangen
2/13/24	58,670	remblokken vooraan	Vervangen
11/30/23	50,604	BMW/MINI voertuigcontrole	Uitvoeren
11/30/23	50,604	service luchtfilter	Uitvoeren
11/30/23	50,604	service microfilter	Uitvoeren
11/30/23	50,604	service motorolie	Uitvoeren
11/30/23	50,604	uitlijnen wielen voor en achter	Afstellen
9/11/23	42,666	remblokken achter	Vervangen
2/22/23	25,983	service microfilter	Uitvoeren
2/22/23	25,983	service motorolie	Uitvoeren