SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Marcel Peeters

2-GEX-157

2-GEX-157 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-GEX-157
Manufacturer	TOYOTA
Model	Corolla Cross
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	103
Fuel Type	Hybrid Gasoline

VIN	JTNADADB50J024231
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	20-11-2024
First Registration	20-11-2024
Odometer	50.111 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images































Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	3 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Small scratch(es)	Polish	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small dent(s)	Restyle	No