



OPEL Combo-E: 8262-MLM

Vinnumber:	W0VEAZKXZJ856577	Versionname:	Cargo L 800kg Eléctrico 100kW Batería 5 furgón derivado de turismo 100kW 3P automática
First Registrationdate:	15/11/2023	Fiscalpower:	
Expertise Mileage:	26522	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Electric		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	1	Rear parking sensors
Number keys remote:	1	
Windows electric F:		
Cruise Control:		
Steering wheel multifunctional:		
Radio multimedia:		
Type of climate control:	Manual climate control	

Tyres

215/65/16/102 H				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/65 R 16 102 H
Tyre size FR				215/65 R 16 102 H
Tyre size RL				215/65 R 16 102 H
Tyre size RR				215/65 R 16 102 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	No
User's manual, Missing, Repair/replace (lump sum)	



Service book, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Seat cover FL, Worn, Replace



Interior, Dirty, Cleaning



Side wall RL, Dent(s) and scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Wing FR, Scratch(es), Acceptable



Tyre repair kit, Missing, Repair/replace (lump sum)




Bumper R, Scratch(es), Acceptable



Boot door panel RL, Scratch(es), Acceptable



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

