



OPEL CORSA: GF-420-LB

Vinnumber:	VXKUPHNKSN4127515	Versionname:	OPEL CORSA 1.2 Turbo 100ch auto Elegance Business VP [5P] bva 8-101CH-5cv (bi-corps)
First Registrationdate:	25/03/2022	Fiscalpower:	
Expertise Mileage:	51202	Power Kw:	74
Bodytype:	Berline	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Semi-leather
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Goodyear: 35%	Fr.R.	Goodyear: 45%
	Re.L.	Continental: 60%	Re.R.	Continental: 60%
Tyre profile depth FL				5.9
Tyre profile depth FR				5.2
Tyre profile depth RL				4.2
Tyre profile depth RR				4.2
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				256
Tyre make RR				256

Assistance equipment


Remote ignition key, Missing, Repair/replace (lump sum)




Interior, Stain, Cleaning



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Wing FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Windscreen, Stone chip(s), Windscreen repair



Wing FR, Dent(s), Repair and paint (complete)



Door RR, Scratch(es), Paint



Luggage cover cord, Incomplete, Replace



Luggage cover cord, Incomplete, Replace



Historique Maintenance

Immatriculation: **GF-420-LB** Date de 1ère immatriculation: **25/03/2022**
Modèle: **Opel CORSA 1.2 Turbo 100ch auto Elegance Business VP [5P] bva 8-101CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
09/12/2025	44.608	STELLANTIS &YOU FRANCE SAS	BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM ET AIR ET BOUGIES
13/12/2024	30.028	STELLANTIS &YOU FRANCE SAS	REVISION
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
	0		LIQUIDE DE FREIN
	0		DISQUES PLAQUETTES AV RPLT
14/08/2023	13.764	STELLANTIS &YOU FRANCE SAS	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR