



**Ford Kuga: L288DZ**

Vinnnumber:	<b>WF0FXXWPMHMM80483</b>	Versionname:	<b>Kuga 2.5 PHEV 165kW Titanium e-CVT</b>
First Registrationdate:	<b>3/05/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>56488</b>	Power Kw:	<b>112</b>
Bodytype:		Body colour:	<b>Solar Silver trendy metaallak</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Parking lot:	<b>560</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Rear parking sensors
GPS		Hook
Autom climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 65 / 17 / 106 / V / Aluminium	3,5 mm	Goodyear	Winter
	Right	225 / 65 / 17 / 106 / V / Aluminium	3,2 mm	Goodyear	Winter
Rear	Left	225 / 65 / 17 / 106 / V / Aluminium	4,2 mm	Goodyear	Winter
	Right	225 / 65 / 17 / 106 / V / Aluminium	4,0 mm	Goodyear	Winter

**Assistance equipment**

Number of charging cables (rapid charge)	<b>1</b>
--	----------

**Service, Maintenance, Execute**



**Interior, Dirty, Cleaning**



**Outer door handle FL, Scratch(es), Repair and paint (complete)**



Door RL, Scratch(es), Repair and paint (complete)



Bumper moulding R, Deformed / Strained, Replace



Bumper trim R, Broken, Replace



Roof, Dent(s), Repair and paint (complete)



Tow bar (fixed), Deformed / Strained, Replace



<b>Kenteken</b>	L288DZ
<b>Merk Model</b>	Ford Kuga 2.5 PHEV 165kW Titanium e-CVT
<b>Brandstofsoort</b>	Benzine
<b>Datum deel1</b>	03-05-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
22-04-25	43.784	APK
22-04-25	43.784	Ruitenwischerblad(en) voorzijde
20-06-23	22.326	Onderhoudsbeurt
11-08-22	10.361	Reparatie band(en)
29-06-22	0	Accu