

INSPECTION REPORT


End of contract

GENERAL INFO

File	315418
License plate	2ATZ751
Vehicle identification number	WAUZZZGY1NA002125
Dossier	2021116138
Make	Audi A3 Ber.30 TFSi 81kW S li.
Mileage	127340
First registration	15/07/2021
client availability date	15/06/2026
inspectionDate	19/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	N
63	Wing Front Left // Painting	N
271	Bumper Front / Trim Left / Replace	N
113	Wing Rear Left // Painting	N
134	Bumper Rear // Repair & Painting	N
281	Bumper Rear / Trim Left / Replace	N
80	Door Front Left // Smart Repair Small	Y
80	Door Front Left // Smart Repair Small	N
103	Door Rear Left // Painting	Y
184	Wing Rear Right // Repair & Painting	N
222	Side View Mirror Right // Painting	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wing Rear Right // Repair & Painting-scratch + dent



Tyre Rear Right // Replace-tear



Door Front Left // Smart Repair Small-dent



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right // Painting-scratch




Wheel Alloy Rear Right // Repair-scratch



Headlight / Front left / Replace-scratch




Wing Front Left // Painting-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Left / Replace-scratch



Wing Rear Left // Painting-scratch



Bumper Rear / Trim Left / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent