MACADAM










Peugeot 208: K590DK

Vinnumber:	**VR3UHZKXZLT130049**	Versionname:	**208 EV 100kW / 50kWh GT**
First Registrationdate:	**30/11/2020**	Fiscalpower:	
Expertise Mileage:	**72533**	Power Kw:	**100**
Bodytype:		Body colour	**Jaune Faro metaallak**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**678**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Panoramic roof	
Autom climate control		Rear parking sensors	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 45 / 17 / 88 / H / Aluminium	4,3 mm	Vredestein	Summer
	Right	205 / 45 / 17 / 88 / H / Aluminium	4,2 mm	Vredestein	Summer
Rear	Left	205 / 45 / 17 / 88 / H / Aluminium	3,7 mm	Michelin	Summer
	Right	205 / 45 / 17 / 88 / H / Aluminium	3,2 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Seat cover FL, Worn, Replace




Door FL, Dent(s) and scratch(es), Repair and paint (complete)





Bonnet, Chemical polution, Polish




Tyre RR, Tear, Replace







Onderhoudshistorie van: VR3UHZKXZLT130049

ALPHABET

Kenteken	K590DK
Merk Model	Peugeot 208 EV 100kW / 50kWh GT
Brandstofsoort	Elektrisch
Datum deel1	11/30/20

Datum reparatie	Kilometerstand	Reparatie omschrijving
3/19/26	64,610	Onderhoudsbeurt
3/19/26	64,610	Remvloeistof
3/19/26	64,610	Tractiebatterij lader
11/7/24	43,167	APK
11/7/24	43,167	Onderhoudsbeurt
11/7/24	43,167	Ruitenwisserblad(en) voorzijde
6/16/23	24,482	Inspuitcomputer
6/16/23	24,482	Tractiebatterij lader
1/4/23	19,668	Onderhoudsbeurt
1/4/23	19,668	Remvloeistof
7/1/22	14,848	Vervanging band
1/12/22	11,014	Reparatie band(en)
11/4/21	9,682	Onderhoudsbeurt