



BMW 218: T144LN

Vinnumber:	WBA11AK0207M90692	Versionname:	218iA100kW Gran coupe
First Registrationdate:	15/07/2023	Fiscalpower:	
Expertise Mileage:	105971	Power Kw:	100
Bodytype:		Body colour	Mineralweiß Metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	750
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 17 / 94 / Y / Aluminium	3,4 mm	Bridgestone	Summer
	Right	225 / 45 / 17 / 94 / Y / Aluminium	2,6 mm	Bridgestone	Summer
Rear	Left	225 / 45 / 17 / 94 / Y / Aluminium	4,7 mm	Bridgestone	Summer
	Right	225 / 45 / 17 / 94 / Y / Aluminium	4,3 mm	Bridgestone	Summer

Assistance equipment

Service, Maintenance, Execute



Wing FL, Bad repair, Repair and paint (complete)



Door FL, Repaired, Check



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Repaired, Check



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Door RR, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check

