



BMW 2 Serie Gran Coupe: HGN03V

Vinnumber:	WBA31GH0X07S59669	Versionname:	220iA 110kW Gran Coupe
First Registrationdate:	8/03/2025	Fiscalpower:	
Expertise Mileage:	47492	Power Kw:	110
Bodytype:		Body colour	Schwarz Uni
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	378
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
GPS		Rear view camera
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 95 / Y / Aluminium	3,6 mm	Maxxis	Summer
	Right	205 / 55 / 17 / 95 / Y / Aluminium	3,4 mm	Maxxis	Summer
Rear	Left	205 / 55 / 17 / 95 / Y / Aluminium	4,6 mm	Maxxis	Summer
	Right	205 / 55 / 17 / 95 / Y / Aluminium	4,0 mm	Maxxis	Summer

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding FR, Broken, Replace and paint



Bonnet, Dent(s), Repair and paint (complete)



Bumper grille, Deformed / Strained, Replace



Door FR, Dent(s), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Kenteken	HGN03V
Merk Model	BMW 220iA 110kW Gran Coupe
Brandstofsoort	Benzine
Datum deel1	08-03-25

Datum reparatie	Kilometerstand	Reparatie omschrijving
07-05-26	37.420	Olie service
07-05-26	37.420	Sleutelbatterij