MACADAM










Toyota Aygo: X768VS

Vinnumber:	**JTDAGNACX00186216**	Versionname:	**Aygo X 1.0 VVT-i 53kW Play MT**
First Registrationdate:	**19/02/2024**	Fiscalpower:	
Expertise Mileage:	**48577**	Power Kw:	**53**
Bodytype:		Body colour	**Night Sky Black metallic**
Gearbox:	**MAN 5 VIT**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Petrol**	Parking lot	**702**
Number of seats	**4**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**1**	Rear view camera	
Manual climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	175 / 65 / 17 / 87 / H / Steel	3,2 mm	Continental	All season
	Right	175 / 65 / 17 / 87 / H / Steel	2,7 mm	Continental	All season
Rear	Left	175 / 65 / 17 / 87 / H / Steel	2,8 mm	Continental	All season
	Right	175 / 65 / 17 / 87 / H / Steel	3,3 mm	Continental	All season

Assistance equipment

Ignition key, Missing, Replace

No pictures to display

Interior, Stain, Cleaning





Door panel RL, Scratch(es), Replace






Door panel RR, Scratch(es), Replace








Outside rear-view mirror housing L, Scratch(es), Polish




Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)






Wing RL, Scratch(es), Repair and paint (complete)




Wheel arch cover RL, Scratch(es), Replace




Bonnet, Scratch(es), Repair and paint (complete)




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)








Door RR, Dent(s) and scratch(es), Repair and paint (complete)







Door FR, Dent(s) and scratch(es), Repair and paint (complete)






Outside rear-view mirror housing R, Scratch(es), Polish




Rear window, Scratch(es), Replace





Bumper R, Scratch(es), Repair and paint (complete)





Onderhoudshistorie van: JTDAGNACX00186216

ALPHABET

Kenteken	X768VS
Merk Model	Toyota Aygo X 1.0 VVT-i 53kW Play MT
Brandstofsoort	Benzine
Datum deel1	2/19/24

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/21/26	48,281	Onderhoudsbeurt
9/17/25	32,752	Onderhoudsbeurt
7/31/24	30	Vervanging band