


Vehicle details

VIN	WVGZZZE2Z NP030490	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh 150kW Pro Auto	Maintenance mileage	-
Registration date	03/03/2022	Year	2022	Exterior Color	Black Metallic
Odometer	125 303 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 235/50/20 Summer 4.5 mm



Pirelli 235/50/20 Summer 4.5 mm



Pirelli 255/45/20 Summer 5.0 mm

Pirelli 255/45/20 Summer 5.0 mm

Exterior

2



Part	Windscreen
Position	-
Damages	Not conform
Severity	-
Repair mode	For info




3



Part	Wing
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



4



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair




5



Part	Alloy wheel 20"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair



6



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair




7



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair



8



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair



9



Part	Wing
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



10



Part	Bumper
Position	Front
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info

