



RENAULT Traffic: 2940-MJM

Vinnumber:	VF1FL000770936689	Versionname:	Furgón L1H1 Blue dCi 96 Kw (130 CV) furgón 96kW 4P manual
First Registrationdate:	26/07/2023	Fiscalpower:	
Expertise Mileage:	115372	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	3		
Number head rests	3		
Type of rims (mounted)	Steel		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options


Number of keys total	2	Radio
Number keys remote	2	Central consol F
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

	205/65/16/107 T			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	4.0			
Tyre profile depth RR	4.0			
Tyre size FL	205/65 R 16 107 T			
Tyre size FR	205/65 R 16 107 T			
Tyre size RL	205/65 R 16 107 T			
Tyre size RR	205/65 R 16 107 T			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	259			
Tyre make RR	259			

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Damaged, Check			





Door panel RR, Scratch(es), Acceptable



Interior, Dirty, Acceptable




MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Wheel cover RL, Missing, Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Grille frame, Broken, Replace



Bumper F, Dent(s) and scratch(es), Replace and paint



Wheel cover FR, Missing, Replace



Outside rear-view mirror housing R, Broken, Replace



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)




Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Rear light R tailgate, Broken, Replace



Boot door panel RL, Dent(s), Repair and paint (complete)



Tyres, No damage, Check





Datos del vehículo

Marca	Matrícula
Modelo	VIN
Versión	

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller