



RENAULT Master: 5034-MRL

Vinnumber:	VF1MA000X72878076	Versionname:	Furgón T L3H2 3500 BI dCi 99kW(135CV) furgón 99kW 4P manual
First Registrationdate:	20/05/2024	Fiscalpower:	
Expertise Mileage:	271003	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	3		
Number head rests	3		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Tow bar
Number keys remote	2	Radio
Windows electric F		Central consol F
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

	225/65/16/112 T			
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				3.0
Tyre profile depth RL				7.0
Tyre profile depth RR				6.0
Tyre size FL				225/65 R 16 112 T
Tyre size FR				225/65 R 16 112 T
Tyre size RL				225/65 R 16 112 T
Tyre size RR				225/65 R 16 112 T
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Interior, Damaged, Check





Door panel RR, Broken, Replace



Interior, Dirty, Cleaning



Seat cover FL, Burned, Replace



User's manual, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)



Rear light L, Broken, Replace



Side wall RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Wing FL, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Door FR, Scratch(es), Paint



Sliding door R, Scratch(es), Paint



Side wall RR, Scratch(es), Paint



Rear light R, Broken, Replace



Internal boot lining R, Broken, Replace



Internal boot lining L, Broken, Replace



Internal boot lining L, Broken, Replace



Boot door panel RR, Scratch(es), Paint



Boot door panel RL, Scratch(es), Paint



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Acceptable

