



PEUGEOT E-208: GT-267-EA

Vinnumber:	VR3UHZKXZPT654419	Versionname:	PEUGEOT E-208 Electrique 136ch Allure Pack VP
First Registrationdate:	20/12/2023	Fiscalpower:	[5P] bva 1-136CH-4cv (bi-corps)
Expertise Mileage:	32793	Power Kw:	100
Bodytype:	Berline	Body colour:	Red
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Electric	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	
Steering wheel leather			
Type of climate control	Autom climate control		
			Lining Other
			Lining Semi-leather

Tyres

	195/55/16/91 V			
Summer tyres:	Fr.L.	Kleber: 30%	Fr.R.	Kleber: 35%
	Re.L.	Kleber: 35%	Re.R.	Kleber: 30%
Tyre profile depth FL				6.2
Tyre profile depth FR				5.9
Tyre profile depth RL				6.0
Tyre profile depth RR				6.1
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Alloy rim RL, Scratch(es), Repair/replace (lump sum)





Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Acceptable



Outer door handle FL, Scratch(es), Polish



Door RL, Dent(s) and scratch(es), Acceptable



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Deformed / Strained, Acceptable



Wing trim RR, Scratch(es), Paint



Door RR, Dent(s), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable



Wing trim FR, Scratch(es), Polish



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Acceptable



Historique Maintenance

Immatriculation: GT-267-EA Date de 1ère immatriculation: 20/12/2023

Modèle: Peugeot E-208 Electrique 136ch Allure Pack VP [5P] bva 1-136CH-4cv (bi-corps)

Date	Kilométrage	Fournisseur	Descriptif
15/07/2025	21.065	SARA	REVISION
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
19/12/2024	13.244	SARA	REVISION