



Mercedes C-Klasse (KKL): 2CAX074

Vinnnumber:	W1K2062541F055643	Versionname:	C300e Break Business Line 2.0i 313pk/cv 5p 9G-Tronic
First Registrationdate:	16/05/2022	Fiscalpower:	
Expertise Mileage:	46903	Power Kw:	150
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+ 50 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/50/17/98 Y			
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				8.0
Tyre profile depth RL				8.0
Tyre profile depth RR				8.0
Tyre size FL				225/50 R 17 98 Y
Tyre size FR				225/50 R 17 98 Y
Tyre size RL				245/45 R 17 99 Y
Tyre size RR				245/45 R 17 99 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Seat cover FR, Stain, Cleaning



Seat cover R, Stain, Cleaning



Bumper F, Dent(s) and scratch(es), Replace and paint



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Sill trim R, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Kenteken	2CAX074
Merk Model	Mercedes C300e Break Business Line 2.0i 313pk/cv 5p 9G-Tronic
Brandstofsoort	Benzine
Datum deel1	5/16/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/25/25	39,211	vergrendelingsmotor (deur, koffer, tank	Vervangen
8/7/25	36,287	batterij	Vervangen
8/7/25	36,287	bougie	Vervangen
8/7/25	36,287	klein materiaal	
8/7/25	36,287	luchtfILTER	Vervangen
8/7/25	36,287	mercedes assyst a	Uitvoeren
8/7/25	36,287	ruitenswisserrubber vooraan	Vervangen
8/7/25	36,287	stoffilter (motor compartiment)	Vervangen
6/20/25	34,237	airco systeem reiniging	Uitvoeren
6/20/25	34,237	batterij	Vervangen
6/20/25	34,237	bougie	Vervangen
6/20/25	34,237	controle niveaus	Uitvoeren
6/20/25	34,237	klein materiaal	
6/20/25	34,237	luchtfILTER	Vervangen
6/20/25	34,237	mercedes assyst a	Uitvoeren
6/20/25	34,237	ruitenswisserrubber vooraan	Vervangen
7/29/24	27,424	batterij	Vervangen
7/29/24	27,424	klein materiaal	Uitvoeren
7/29/24	27,424	mercedes assyst b	Uitvoeren
7/29/24	27,424	ruitenswisserrubber achter	Vervangen
7/29/24	27,424	ruitenswisserrubber vooraan	Vervangen
12/18/23	1	pechverhelping buitenland	Uitvoeren
7/10/23	13,112	airco systeem reiniging	Uitvoeren
7/10/23	13,112	klein materiaal	Uitvoeren
7/10/23	13,112	mercedes assyst a	Uitvoeren
7/10/23	13,112	ruitenswisserrubber achter	Vervangen
7/10/23	13,112	ruitenswisserrubber vooraan	Vervangen
7/10/23	13,112	stoffilter (motor compartiment)	Vervangen