APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	AUDI
Model / version:	A3 BERLINE
Vin:	WAUZZZGYXNA010997
Plate:	2BDH202
Mileage:	143315
First registration:	11/10/2021
Color:	Glacier Whit

ADDITIONAL INFORMATION



Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	1
Original key:	✓

PICTURES












































VIN INFORMATION

6 haut-parleurs	Téléphone	Boîte manuelle
6 rapports	Equipement S-Line	Matière : alliage
Lettre repère (J)	Diamètre avant 17	Diamètre arrière 17
Largeur avant 8,0	Largeur arrière 8,0	Diamètre avant 17
Diamètre arrière 17	Hauteur avant 45	Hauteur arrière 45
Indice de vitesse avant Y	Indice de vitesse arrière Y	Largeur avant 225
Largeur arrière 225	Climatisation	Climatisation réfrigérant 1234YF
Accoudoir central avant	Essence	1498 cm3
1.50 litre	110 kw	150 ch
Euro 6	Effet perle vernissée	Rétroviseur gauche asphérique
Suspension sport	Aide au stationnement arrière	Caméra avant

Affichage lecture des panneaux de signalisation	Appel de secours	Pare-brise teinté dégradé
Airbag passager	Airbag passager désactivable	Freinage d'urgence assistée autonome (urbain)
depuis 08.21	triangle de secours dans le couvercle de coffre	radio avec récepteur numérique
garnissage tissu Index	extincteur	enjoliveurs bas de caisse éclairés
barre stabilisatrice ar 20 mm	205/55 R 17 .. W	système de gonflage des pneus
barre stabilisatrice av 24 mm	suspension ar à 4 bras	sidebag av/ar avec airbag pour la tête et airbag central av
réservoir à charbon actif (EVAP)	freins av 288x25	FREINS AR 272X10

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	?	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	?
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:		**Fast charging cables:**	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Winter		?
Front right	5 mm			Winter		?
Rear left	5 mm			Winter		?
Rear right	5 mm			Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key	Missing
3	Alloy rim FL	Scratch(es)
4	Wing RL	Dent(s) and scratch(es)
5	Tyre repair kit - Compressor	Missing
6	Wing RR	Dent(s)
7	Alloy rim RR	Scratch(es)
8	Alloy rim FR	Scratch(es)

Total: 7

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Damaged	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Contact key - Missing




3 - Alloy rim FL - Scratch(es)






4 - Wing RL - Dent(s) and scratch(es)





5 - Tyre repair kit - Compressor - Missing



6 - Wing RR - Dent(s)










7 - Alloy rim RR - Scratch(es)





8 - Alloy rim FR - Scratch(es)





2 - Bodywork - Damaged - Renta®











SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

29/09/2026 14:02

