APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	RENAULT
Model / version:	MGANE GRANDTOUR
Vin:	VF1RFB00X70642851
Plate:	2DGE739
Mileage:	110733
First registration:	09/03/2023
Color:	Highland Gre

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES






















































VIN INFORMATION

Projecteurs à LED	Projecteurs antibrouillard	Feux avant de jour à LED
Code équipement EA3	Matière : alliage	Lettre repère (J)
Diamètre avant 17	Diamètre arrière 17	Largeur avant 7,0
Largeur arrière 7,0	Diamètre avant 17	Diamètre arrière 17
Hauteur avant 50	Hauteur arrière 50	Indice de vitesse avant V
Indice de vitesse arrière V	Largeur avant 205	Largeur arrière 205
Roue de secours tôle	Finition intérieure Harmonie 1	Climatisation automatique
Climatisation réfrigérant 1234YF	Pare-soleil conducteur éclairé	Pare-soleil passager éclairé
Essence	1333 cm3	1.30 litre
103 kw	140 ch	Euro 6
Métallisée vernissée	Frein à main électrique	Rétroviseur gauche à réglage électrique

Rétroviseur droit à réglage électrique	Rétroviseur intérieur jour/nuit automatique	Garnitures tissu
Aide au stationnement avant	Aide au stationnement arrière	Caméra avant
Caméra arrière de recul	Régulateur et limiteur de vitesse	Affichage lecture des panneaux de signalisation
Carte mains libres	Lève-vitres arrière électriques à impulsion	Alarme
Appel de secours	Lunette arrière teintée foncée	Vitres portes arrière teintées foncées
Vitres de custode teintées foncées	détecteur de pluie essuie-vitre	Fixotoit
Airbag latéraux avant	Airbag rideaux avant	Airbag rideaux arrière
Protection piéton	Alerte franchissement de ligne (AFIL)	Assistant maintien de la voie
Freinage d'urgence assistée autonome (urbain)	depuis 01.23	sièges ar "Easy Break System" (SGAR03/SGAR04)
tableau de bord numérique + indicateurs analogiques (MET04)	Micro Hybrid (HYB01)	6 vitesses TL4
suspension durcie 1 (TRSEV1)	période de documentation 2019 (M2019/PHAS2)	7 J x 17 Alu Et 43 (RALU17)

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		205/50R17 93V	All-seasons		?
Front right	5 mm		205/50R17 93V	All-seasons		?
Rear left	5 mm		205/50R17 93V	All-seasons		?
Rear right	5 mm		205/50R17 93V	All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot cover	Grooved
3	Seat cover FR	Dirty
4	Contact key - Boordcomputer resetten	Not original part
5	Alloy rim FR polished	Grooved
7	Roof	Scratch(es)

Total: 5

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Cover insulation - Marterschade	Damaged	✓	×	×
6	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 2

DAMAGES DETAILS

1 - Boot cover - Grooved







3 - Seat cover FR - Dirty




4 - Contact key - Boordcomputer resetten - Not original part





5 - Alloy rim FR polished - Grooved






7 - Roof - Scratch(es)





2 - Cover insulation - Marterschade - Damaged - Renta®




6 - Bodywork - Dent(s) and scratch(es) - Renta®









SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

22/10/2026 11:26