MACADAM









RENAULT CLIO: GJ-634-ED

Vinnumber:	**VF1RJA00469641147**	Versionname:	**RENAULT CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**
First Registrationdate:	**30/08/2022**	Fiscalpower:	
Expertise Mileage:	**62123**	Power Kw:	**66**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/55/16/87 H**			
	Fr.L.	**Bridgestone: 80%**	Fr.R.	**Bridgestone: 80%**
	Re.L.	**Bridgestone: 45%**	Re.R.	**Bridgestone: 40%**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.1**
Tyre profile depth RL	**5.3**
Tyre profile depth RR	**5.5**
Tyre size FL	**195/55 R 16 87 H**
Tyre size FR	**195/55 R 16 87 H**
Tyre size RL	**195/55 R 16 87 H**
Tyre size RR	**195/55 R 16 87 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior covering B pillar R, Scratch(es), Replace







Interior covering B pillar R, Scratch(es), Replace









Door panel FR, Scratch(es), Replace










Glove compartment lid, Scratch(es), Replace





Seat cover FR, Stain, Cleaning




Seat cover FL, Stain, Cleaning




Roof liner, Tear, Replace











Door panel RR, Scratch(es), Replace



Door panel RL, Scratch(es), Replace



Tyre FL, Out of tolerance, Replace



Tyre RL, Tear, Replace



Tyre FR, Out of tolerance, Replace



Wing FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)






Wing RL, Scratch(es), Polish




Bumper F, Scratch(es), Paint










Bumper grille, Unclasped, Dismount/Mount




Bumper grille, Unclasped, Dismount/Mount




Brand badge F, Broken, Replace




Bonnet, Chemical polution, Polish




Door RR, Dent(s) and scratch(es), Repair and paint (complete)








Door FR, Dent(s) and scratch(es), Repair and paint (complete)




Outside rear-view mirror base R, Broken, Replace



Outside rear-view mirror housing R, Bad repair, Paint



Internal boot lining L, Broken, Replace



Internal boot lining R, Broken, Replace



Boot lid covering R, Scratch(es), Replace



Rear bulkhead lining, Scratch(es), Replace





Bumper R, Scratch(es), Paint






Rear light L, Scratch(es), Replace




Rear light R, Scratch(es), Replace




Tailgate / Boot, Dent(s), Repair and paint (complete)





ALPHABET

Historique Maintenance

Immatriculation: **GJ-634-ED** Date de 1ère immatriculation: **30/08/2022**

Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
07/10/2026	61.046	ECOUEN AUTOMOBILES	LIQUIDE DE FREIN
			REVISION
			BALAI ESSUIE GLACE AR
			DISQUES PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
19/08/2026	58.098	FLEET SOLUTIONS FRANCE	DIAG
			FILTRE A AIR RPLT
			FILTRE CLIM RPLT
			BOUGIES ALLUMAGE RPLT
			REVISION
13/07/2026	57.486	ECOUEN AUTOMOBILES	DIAG
22/08/2025	42.439	FLEET SOLUTIONS FRANCE	REVISION ET CLIM
18/09/2024	28.312	ECOUEN AUTOMOBILES	BALAIS ESSUIE GLACE AV
			PLAQUETTES AV RPLT
			REVISION ET CLIM
27/10/2023	14.265	NORAUTO SAS (PRODUIT SPE)	REVISION ET CLIM