
APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	MAZDA
Model / version:	MX-30
Vin:	JMZDR1WBJ00200676
Plate:	2CLT539
Mileage:	40121
SOH:	94 %
First registration:	08/09/2022
Color:	Polymetal Gr


ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	✓

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	?


PICTURES



















































VIN INFORMATION

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	2 mm		215/55R18 99V	Summer	Aluminium	×
Front right	2 mm		215/55R18 99V	Summer	Aluminium	×
Rear left	6 mm		215/55R18 99V	Summer	Aluminium	×
Rear right	6 mm		215/55R18 99V	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Wing RR	Dent(s) and scratch(es)
3	Windscreen	

Total: 2


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Scratch(es)	✓	×	×


Total: 1

DAMAGES DETAILS


2 - Wing RR - Dent(s) and scratch(es)


3 - Windscreen

1 - Bodywork - Scratch(es) - Renta®










SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

12/10/2026 10:35

