



RENAULT Clio: 2716-MPX

Vinnumber:	VF1RJA00172210758	Versionname:	Evolution dCi 100 (74kw) berlina con portón 74kW 5P manual
First Registrationdate:	24/04/2024	Fiscalpower:	
Expertise Mileage:	201002	Power Kw:	
Bodytype:	Berline	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Radio
Number keys remote	2	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Manual climate control	

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Damaged, Replace			



Interior, Damaged, Check



Interior, Dirty, Cleaning



Registration document, Missing, Repair/replace (lump sum)



Wing FL, Scratch(es), Acceptable



Wheel cover FL, Missing, Replace



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover RL, Missing, Replace



Bumper F, Scratch(es), Acceptable





Bumper moulding FR, Missing, Replace and paint



Wheel cover FR, Missing, Replace



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wheel cover RR, Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

