



**VOLKSWAGEN TOURAN**

Vinnumber:	<b>WVGZZZ1TZLW008431</b>	Versionname:	<b>1.5 TSi Highline</b>
First Registrationdate:	<b>26/09/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>180242</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2620</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>No Tow bar</b>
Type of Lining	<b>Lining semi-Alcantara</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

<b>205/60/16/92 H</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/60 R 16 92 H</b>
Tyre size FR				<b>205/60 R 16 92 H</b>
Tyre size RL				<b>205/60 R 16 92 H</b>
Tyre size RR				<b>205/60 R 16 92 H</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>879,98</b>
Seat cover FL, Damaged, Acceptable	<b>0,00</b>



Seat cover FL, Stain, Cleaning 29,16



Backrest cover FL, Worn, Acceptable 0,00



Seat cover FR, Stain, Cleaning 29,16



Bumper F, Scratch(es), Repair and paint (complete) 296,58



Bonnet, Stone chip(s), Acceptable 0,00



Windscreen, Scratch(es), Polish 0,00



Windscreen, Repaired, Acceptable 0,00




Bumper R, Scratch(es), Repair and paint (complete) 296,58





Rear window, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Door FR, Scratch(es), Acceptable 0,00



Wing RR, Bad repair, Check 0,00



Wing RR, Dent(s), Paintless dent repair 95,47



Step R, Dent(s), Acceptable 0,00



Bodywork, Not original part, Remove lettering 0,00

