



DS 7 CROSSBACK: FY-724-KF

Vinnumber:	VR1J45GBUMY503189	Versionname:	DS DS 7 CROSSBACK E-TENSE 4x4 300 PERFORMANCE Line + VP [5P] bva 8-300CH-11cv (SUV)
First Registrationdate:	6/04/2021	Fiscalpower:	
Expertise Mileage:	58388	Power Kw:	221
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Semi-leather Lining Alcantara

Tyres

235/50/19/99 H				
Summer tyres:	Fr.L.	Continental: 35%	Fr.R.	Continental: 40%
	Re.L.	Continental: 55%	Re.R.	Continental: 60%
Tyre profile depth FL				6.0
Tyre profile depth FR				5.7
Tyre profile depth RL				4.7
Tyre profile depth RR				4.3
Tyre size FL				235/50 R 19 99 H
Tyre size FR				235/50 R 19 99 H
Tyre size RL				235/50 R 19 99 H
Tyre size RR				235/50 R 19 99 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Interior, Dirty, Cleaning





Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Scratch(es), Paint



Bumper R, Scratch(es), Polish



Historique Maintenance

Immatriculation: **FY-724-KF**Date de 1ère immatriculation: **06/04/2021**Modèle: **DS 7 CROSSBACK E-TENSE 4x4 300 PERFORMANCE Line + VP [5P] bva 8-300CH-11cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
26/05/2026	58.036	GARAGE MATHAIS***	BATTERIE RPLT
	0		BATTERIE RPLT
	0		SERRURE DE COFFRE RPLT
	0		RECYCLAGE
	0		SERRURE DE COFFRE RPLT
14/11/2025	50.267	GARAGE MATHAIS***	PERMUTATIONS PNEUS
	0		GARDIENNAGE
02/06/2025	46.868	TRUJAS SAS	LIQUIDE DE FREIN
	0		BATTERIE RPLT
	0		FILTRE CLIM RPLT
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		DIVERS CLIM
	0		FILTRE A AIR RPLT
02/05/2025	45.794	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
16/04/2025	45.011	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
18/12/2024	41.563	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
12/06/2024	35.291	STELLANTIS &YOU FRANCE SAS	BOITIER D ALLUMAGE RPLT
	0		RECYCLAGE
	0		REVISION
03/05/2024	34.335	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		REPLACEMENT PNEUS ETE
	0		PERMUTATIONS PNEUS
05/12/2023	28.652	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
12/05/2023	19.416	STELLANTIS &YOU FRANCE SAS	BALAI ESSUIE GLACE AR
	0		REVISION

Historique Maintenance

Immatriculation: **FY-724-KF**

Date de 1ère immatriculation: **06/04/2021**

Modèle: **DS 7 CROSSBACK E-TENSE 4x4 300 PERFORMANCE Line + VP [5P] bva 8-300CH-11cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
28/04/2023	19.271	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
20/12/2022	15.074	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
10/05/2022	10.151	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
06/05/2022	10.133	STELLANTIS &YOU FRANCE SAS	REVISION
22/02/2022	8.084	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		REPLACEMENT PNEUS HIVER