MACADAM







OPEL Combo: 8738-MGZ

Vinnumber:	**W0VEFYHT2PN524491**	Versionname:	**1.5 TD 75kW (100CV) Express L H1 650kg furgón derivado de turismo 75kW 3P manual**
First Registrationdate:	**25/05/2023**	Fiscalpower:	
Expertise Mileage:	**55244**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**No**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/65/15/91 H**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Continental: 3 mm**	Re.R.	**Continental: 3 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**195/65 R 15 91 H**
Tyre size FR	**195/65 R 15 91 H**
Tyre size RL	**195/65 R 15 91 H**
Tyre size RR	**195/65 R 15 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Door panel RR, Scratch(es), Replace




Interior, Dirty, Cleaning




MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Malfunction indicator, Blinking, Check




Indicator FL, Missing, Replace




Steel rim FL, Deformed / Strained, Replace




Outside rear-view mirror housing L, Scratch(es), Paint




Side window trim RL, Broken, Replace




Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)




Rear light L, Broken, Replace




Bumper F, Scratch(es), Paint






Bumper F, Scratch(es), Paint




Tyre RR, Worn, Acceptable




Rear light R, Broken, Replace




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)




Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)




Door FR, Dent(s), Paintless dent repair




Internal boot lining L, Scratch(es), Replace




Rear panel, Scratch(es), Repair and paint (complete)




Bumper moulding RL, Crack, Repair and paint (complete)




Boot door panel RL, Crack, Replace and paint




Tailgate handle, Missing, Replace





Bumper R, Scratch(es), Paint




Tyres, No damage, Check






Bodywork, Glue residues, Remove lettering




ALPHABET

Datos del vehículo

Marca	OPEL	Matrícula	8738-MGZ
Modelo	Combo	VIN	W0VEFYHT2PN524491
Versión	1.5 TD 75kW (100CV) Express L H1 650kg furgón derivado de turismo 75kW 3P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
11/05/2026	Luna Custodia (triangulo) y fijos	0	CRISTALBOX ZARAGOZA (MARIANO BARBASAN)
15/04/2026	Luna Custodia (triangulo) y fijos	0	CRISTALBOX ZARAGOZA (MARIANO BARBASAN)
12/05/2025	Pilotos, Limpiaparabrisas delantero	1010	Talleres V. Longares
25/07/2024	Rev. 24.000 kms	22318	TALLERES AUTO-CADRETE S.L.
02/10/2024	Alineado, Sustitución	26916	EXPO TYRE
21/11/2024	Luna parabrisas | Luna Custodia (triangulo) y fijos DE PUERTA DELANTERA DERECHA	29083	RALARSA HOLDING S.L.
21/03/2025	Lampara H7 DD	34099	PLATAFORMA COMERCIAL RETAIL ZARAGOZA – CRTA. MADRID
23/07/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Filtro aceite - Nueva, Filtro aire - Nueva, Filtro antipolen, Filtro combustible, Líquido lavaparabrisas - -20ºC - Nueva, Serv inspección 40000 KM, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Filtro combustible, Tasa de gestión de aceites usados	39525	STELLANTIS & YOU ESPAÑA S.A.
04/03/2026	Reparación pinchazo	41411	EXPO TYRE 2005 S.L.
05/12/2025	Pastillas freno dl - EQUIVALENTE EN EUROREPAR - Economic, Sustituir Pastillas freno dl	46133	STELLANTIS & YOU ESPAÑA S.A.

Fecha	Descripción	Kilómetros	Taller