



Peugeot 308 (UKL): 2CFR195

Vinnnumber:	VR3FCYHZLNY561342	Versionname:	308 SW Active Pack 1.5 BlueHDi S&S 130pk/cv 5p
First Registrationdate:	6/07/2022	Fiscalpower:	
Expertise Mileage:	72568	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar fixed
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/94 V			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Damaged, Acceptable



Bumper F, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Kenteken	2CFR195
Merk Model	Peugeot 308 SW Active Pack 1.5 BlueHDi S&S 130pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	7/6/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/15/26	67,435	onderhoud 4e jaar	Uitvoeren
4/7/25	43,181	luchtfilter interieur	Vervangen
4/7/25	43,181	oliezeef	Vervangen
4/7/25	43,181	onderhoud 3e jaar	Uitvoeren
3/22/24	29,029	30000 km	Uitvoeren
3/22/24	29,029	luchtfilter interieur	Vervangen
3/22/24	29,029	oliezeef	Vervangen
3/22/24	29,029	remvloeistof	Vervangen