



BMW 3 Touring

Vinnumber:	WBA6N31090FM38022	Versionname:	
First Registrationdate:	7/04/2022	Fiscalpower:	
Expertise Mileage:	163402	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	4806
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	Tow bar removable
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

225/50/17/98 Y				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				225/50 R 17 98 Y
Tyre size FR				225/50 R 17 98 Y
Tyre size RL				225/50 R 17 98 Y
Tyre size RR				225/50 R 17 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Total cost ex VAT	8056,93
Seat cover FR, Stain, Cleaning	29,16



Seat cover R, Stain, Cleaning 29,16



Seat cover FL, Stain, Cleaning 29,16



Headlight R, Broken, Replace 1528,48



Bumper F, Dent(s) and scratch(es), Replace and paint 992,55



Bumper moulding F, Broken, Replace 122,98



Bumper moulding F, Broken, Replace 53,44



Bonnet, Dent(s) and scratch(es), Replace and paint 1360,19



Alloy rim FL, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete) 356,09



Door FR, Dent(s) and scratch(es), Replace and paint 1511,03



Door RR, Dent(s) and scratch(es), Replace and paint 1480,08



Wing RR, Scratch(es), Repair and paint (complete) 431,58



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03

