



TESLA MODEL Y Long-Range Dual Motor AWD

-	
VIN	XP7YGCEK5PB151033
Première immatriculation	23/06/2023
Kilométrage véhicule	75 191 km

DÉTAILS DE L'INSPECTION

Date de l'inspection	22/07/2026 10:17:34	Adresse d'inspection	BCA TOULOUSE
----------------------	---------------------	----------------------	--------------

INFORMATIONS SUR LE VÉHICULE

Marque	TESLA	Transmission	Avant
Modèle	MODEL Y Long-Range Dual Motor AWD	Nbre sièges	5
VIN	XP7YGCEK5PB151033	Nombre appuis-têtes	4
Première immatriculation	23/06/2023	Couleur intérieur	Noir
Type de carrosserie	Berline	Couleur carrosserie	Noir
Nbre portes	5	Catégorie	Vehicule particulier
Type de carburant	Electrique	Couleur tableau de bord	Noir
Boîte de vitesses	Automatique		

DOCUMENTS ET CLÉS

Nbre clés total	1	Certificat immatriculation (original)	Non
Nbre clés télécommandes	1	Certificat immatriculation (original)	N/A

OPTIONS

Vitres électriques AV	Oui	Radar parking AV	Oui
Vitres électriques AR	Oui	Radar parking AR	Oui
Régulateur de vitesse	Oui	Phares Xenon/LED/Laser	Oui
Volant multifonctions	Oui	Type de climatisation	Clim. automatique
Sièges chauffants AV	Oui	Camera de recul	Oui
Sièges électriques AVG	Oui	Nature de peinture	Metallisé
Toit panoramique	Oui		

DAMAGES

Exterior




1 | Tyre FL

Damage type	Out of tolerance
Repair mode	Replace



2 | Tyre FR

Damage type	Out of tolerance
Repair mode	Replace



3 | Alloy rim RR > 16"

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



4 | Alloy rim RL > 16"

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)





5 | Alloy rim RR > 16"

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



6 | Alloy rim FR > 16"

Damage type	Scratch(es)
Repair mode	Replace



7 | Wheel cover FR

Damage type	Missing
Repair mode	Replace




8 | Door FL

Damage type	Scratch(es)
Repair mode	Polish



9 | Bumper F

Damage type	Scratch(es)
Repair mode	Paint



10 | Daytime running light FR

Damage type	Scratch(es)
Repair mode	Replace



11 | Wing FR

Damage type	Scratch(es)
Repair mode	Paint



12 | Wing trim FR

Damage type	Scratch(es)
Repair mode	Replace



13 | Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Polish



14 | Door RR

Damage type	Scratch(es)
Repair mode	Paint



15 | Bumper R

Damage type	Scratch(es)
Repair mode	Acceptable



16 | Tailgate / Boot

Damage type	Scratch(es)
Repair mode	Paint

Commercial photos

