



PEUGEOT 2008

Immatriculation	-
VIN	VR3USHNSSNJ772620
Kilométrage	48 598 km
Première immatriculation	17/11/2022
Couleur carrosserie	Gris

DÉTAILS DE L'INSPECTION

Adresse d'inspection _____ Date de l'inspection **11/05/2026 16:00:41**

Adresse d'inspection _____

INFORMATIONS SUR LE VÉHICULE

Marque	PEUGEOT	Type de carrosserie	SUV
Modèle	2008	Nbre portes	5
VIN	VR3USHNSSNJ772620	Nbre sièges	5
Première immatriculation	17/11/2022	Transmission	Avant
Kilométrage	48 598 km	Couleur intérieur	Noir
Catégorie	Vehicule particulier	Couleur carrosserie	Gris

DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Manuel d'utilisation	Oui
Nbre clés total	2	Certificat immatriculation (original)	Copie
Nbre clés télécommandes	2	Certificat immatriculation (original)	Non

OPTIONS

Batterie fonctionnante	Oui	Camera de recul	Oui
Moteur fonctionnant	Oui	Cache bagages	Oui
Véhicule roulant	Oui	Compresseur	Oui
Niveau carburant	75	Kit réparation	Oui
GPS	Oui	Nature de peinture	Metallisé

PNEUS

Pneus montés

Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	7,0 mm	Autre	215/60 R 17 96 H	4 Saisons	Aluminium	Non
Avant	Droite	7,1 mm	Autre	215/60 R 17 96 H	4 Saisons	Aluminium	Non
Arrière	Gauche	7,3 mm	Autre	215/60 R 17 96 H	4 Saisons	Aluminium	Non
Arrière	Droite	7,1 mm	Autre	215/60 R 17 96 H	4 Saisons	Aluminium	Non

DAMAGES



Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Door RL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Door RR

Damage type	Scratch(es)
Repair mode	Paint



Tailgate / Boot

Damage type	Bad repair
Repair mode	Paint



Number plate R

Damage type	Deformed / Strained
Repair mode	Repair/replace (lump sum)



Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Acceptable



Wing FL

Damage type	Scratch(es)
Repair mode	Polish



Bumper spoiler F

Damage type	Scratch(es)
Repair mode	Acceptable



Bumper moulding F

Damage type	Scratch(es)
Repair mode	Acceptable



Bumper moulding FR

Damage type	Scratch(es)
Repair mode	Acceptable



Bumper F

Damage type	Scratch(es)
Repair mode	Polish



Wing trim FR

Damage type	Scratch(es)
Repair mode	Acceptable



Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Polish



Door FR

Damage type	Dent(s)
Repair mode	Acceptable



Bumper R

Damage type	Scratch(es)
Repair mode	Acceptable

COMMERCIAL PHOTOS

