



CITROËN Jumper: 2631-MKP

Vinnumber:	VF7YCBPFB12X83840	Versionname:	Citroen BlueHdi 103KW (140CV) Furgón 35L2H2 furgón 103kW 4P manual
First Registrationdate:	28/09/2023	Fiscalpower:	
Expertise Mileage:	186134	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	No		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	1	Radio:	
Number keys remote:	1	Central consol F:	
Windows electric F:		Rear parking sensors:	
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

215/70/15/109 S				
Summer tyres:	Fr.L.	Falken: 7 mm	Fr.R.	Falken: 7 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm
Tyre profile depth FL:				7.0
Tyre profile depth FR:				7.0
Tyre profile depth RL:				8.0
Tyre profile depth RR:				8.0
Tyre size FL:				215/70 R 15 109 S
Tyre size FR:				215/70 R 15 109 S
Tyre size RL:				215/70 R 15 109 S
Tyre size RR:				215/70 R 15 109 S
Tyre make FL:				1957074
Tyre make FR:				1957074
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Door panel RR, Broken, Replace			



Door panel RL, Broken, Replace



Interior, Damaged, Check



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door L, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Door FR, Scratch(es), Paint



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check

