



VOLKSWAGEN TIGUAN ALLSPACE: GK-288-AS

Vinnumber:	WVGZZZ5N0NM172319	Versionname:	VOLKSWAGEN TIGUAN ALLSPACE 2.0 TDI 150 BMV6
First Registrationdate:	17/10/2022	Fiscalpower:	Life VP [5P] bvm 6-150CH-8cv (SUV)
Expertise Mileage:	63582	Power Kw:	110
Bodytype:	SUV	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Sun Roof electric	
GPS big screen color		Panoramic roof	
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of climate control	Autom climate control	Roof bar black	
		Rear view camera	
		Seat cover lining	Lining Leather

Tyres

	235/55/18/100 V			
Summer tyres:	Fr.L.	Continental: 90%	Fr.R.	Continental: 85%
	Re.L.	Continental: 55%	Re.R.	Continental: 60%
Tyre profile depth FL				2.0
Tyre profile depth FR				2.5
Tyre profile depth RL				4.5
Tyre profile depth RR				4.4
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Inner door sill RR, Scratch(es), Paint



Tyre FL, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Replace



Tyre FR, Out of tolerance, Replace



Wing trim FL, Unclasp(ed), Dismount/Mount



Outside rear-view mirror housing L, Scratch(es), Paint



Wing RL, Scratch(es), Paint



Door RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Wing FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Replace



Bumper moulding FR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Door RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GK-288-AS** Date de 1ère immatriculation: **17/10/2022**

Modèle: **Volkswagen TIGUAN ALLSPACE 2.0 TDI 150 BMV6 Life VP [5P] bvm 6-150CH-8cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
05/02/2026	53.962	ADVANCE	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		ADBLUE
24/10/2024	27.030	ADVANCE	REVISION
	0		PLAQUETTES AR RPLT
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		PLAQUETTES AV RPLT