



DS 7 Crossback:

Vinnumber:	VR1JCYHZRKY098085	Versionname:	
First Registrationdate:	20/08/2019	Fiscalpower:	
Expertise Mileage:	101844	Power Kw:	
Bodytype:		Body colour:	Red
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3226
Fueltype:	Diesel		
Maintenance:	NOT OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	Tow bar removable
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

235/55/18/100 V				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	859,96
Service, Maintenance, Check:	0,00



Windscreen, Bad repair, Replace 655,75



Door FL, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Acceptable 0,00




Alloy rim RL polished, Chemical polution, Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00




Door RR, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Alloy rim RR polished, Chemical polution, Acceptable 0,00

