



## CITROËN GRAND C4 SPACETOURER

Vinnumber:	<b>VF73AYHZ2MJ566327</b>	Versionname:	<b>1.5 BlueHDi 130 S&amp;S MAN6 Business Lounge</b>
First Registrationdate:	<b>26/02/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>104200</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3511</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

## Options

Number of keys total:	<b>2</b>	Seats electric F L:	
Cruise Control:		Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Seats F heated:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

## Limited Technical Inspection

## Tyres

205/55/17/95 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>205/55 R 17 95 V</b>
Tyre size FR				<b>205/55 R 17 95 V</b>
Tyre size RL				<b>205/55 R 17 95 V</b>
Tyre size RR				<b>205/55 R 17 95 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

## Assistance equipment

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	<b>2933,29</b>
Interior, Worn, Acceptable:	<b>0,00</b>



Door panel RR, Scratch(es), Smart repair 116,69



Backrest cover RR, Tear, Replace 1496,51



Door panel RL, Scratch(es), Smart repair 116,69



Bumper F, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



A-pillar left, Dent(s) and scratch(es), Spot repair 148,33



Door FL, Dent(s) and scratch(es), Acceptable 0,00



Internal boot lining R, Scratch(es), Smart repair 116,69



Internal boot lining L, Scratch(es), Smart repair 116,69



Boot lid covering R, Scratch(es), Smart repair 116,69



Rubber seal for boot lid, Deformed / Strained, Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Rear window, Scratch(es), Acceptable 0,00



Step R, Dent(s) and scratch(es), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



Outer door handle FR, Scratch(es), Acceptable 0,00



Wing FR, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21

