



PEUGEOT 208: GA-777-XB

Vinnumber:	VR3UPHNEKMT072730	Versionname:	PEUGEOT 208 PureTech 100 S&S Allure Business VP [5P] bvm 6-100CH-5cv (bi-corps)
First Registrationdate:	22/07/2021	Fiscalpower:	
Expertise Mileage:	92975	Power Kw:	75
Bodytype:	Berline	Body colour:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options


Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			Lining Leather
Type of climate control	Autom climate control		

Tyres

195/55/16/87 H			
Winter tyres:	Fr.L.	Continental: 75%	Fr.R.
	Re.L.	Goodyear: 35%	Re.R.
			Goodyear: 45%
Tyre profile depth FL			3.5
Tyre profile depth FR			3.0
Tyre profile depth RL			5.8
Tyre profile depth RR			5.3
Tyre size FL			195/55 R 16 87 H
Tyre size FR			195/55 R 16 87 H
Tyre size RL			195/55 R 16 87 H
Tyre size RR			195/55 R 16 87 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			259
Tyre make RR			259

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Remote ignition key (no insert), Missing, Repair/replace (lump sum)			



Interior, Stain, Cleaning



Tyre FL, Out of tolerance, Replace




Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Unclasp(ed), Dismount/Mount



Wing RR, Scratch(es), Paint



Bumper moulding R, Deformed / Strained, Replace



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GA-777-XB** Date de 1ère immatriculation: **22/07/2021**

Modèle: **Peugeot 208 PureTech 100 S&S Allure Business VP [5P] bvm 6-100CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
27/04/2026	88.192	DEKRA AUTOMOTIVE TRAPPES	CONTROLE TECHNIQUE
11/07/2025	74.754	STELLANTIS &YOU FRANCE SAS	REVISION
	0		PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		DIVERS CLIM
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
02/10/2024	60.259	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
22/03/2024	44.901	SOCIETE LANDAISE DE COMMERCE AUTO	BOITIER D ALLUMAGE RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		REVISION
21/11/2022	20.138	ABCIS POITOU BY AUTOSPHERE	RECYCLAGE
	0		BALAI ESSUIE GLACE AV AR
	0		BALAI ESSUIE GLACE AV AR
	0		FILTRE CLIM RPLT
	0		REVISION