



CITROËN C3 SOCIÉTÉ GD-278-DS

Vinnumber:	VF7SWYHTUMT588511	Versionname:	CITROËN C3 SOCIÉTÉ BlueHDi 100 S&S
First Registrationdate:	25/11/2021	Fiscalpower:	BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)
Expertise Mileage:	127350	Power Kw:	75
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	VS		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	205/55/16/91 T			
Summer tyres:	Fr.L.	Goodyear: 50%	Fr.R.	Goodyear: 60%
	Re.L.	Goodyear: 15%	Re.R.	Goodyear: 25%
Tyre profile depth FL				5.0
Tyre profile depth FR				4.3
Tyre profile depth RL				7.3
Tyre profile depth RR				6.6
Tyre size FL				205/55 R 16 91 T
Tyre size FR				205/55 R 16 91 T
Tyre size RL				205/55 R 16 91 T
Tyre size RR				205/55 R 16 91 T
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)	





Inner door sill FR, Scratch(es), Paint



Wheel cover FL, Deformed / Strained, Replace



Door lock FL, Strained, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RL, Scratch(es), Replace



Door trim FL, Scratch(es), Replace



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Missing, Replace



Bumper F, Broken, Replace and paint



Door FR, Scratch(es), Paint



Door RR, Dent(s), Repair and paint (complete)



Wing trim RR, Scratch(es), Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle RR, Scratch(es), Paint



Outside rear-view mirror base R, Broken, Replace and paint



Rear bulkhead lining, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: GD-278-DS Date de 1ère immatriculation: 25/11/2021

Modèle: Citroen C3 SOCIÉTÉ BlueHDi 100 S&S BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)

Date	Kilométrage	Fournisseur	Descriptif
16/01/2026	124.549	CAR AVENUE BAILLY	CONTROLE TECHNIQUE
23/10/2025	118.273	CAR AVENUE BAILLY	FILTRE CLIM RPLT
	0		REVISION
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		DIVERS CLIM
	0		REVISION
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		LAMPE RPLT
17/10/2024	90.152	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS HIVER
25/09/2024	89.119	CAR AVENUE BAILLY	BALAIS ESSUIE GLACE AV
	0		REVISION
	0		DISQUES PLAQUETTES AV RPLT
	0		ADBLUE
07/11/2023	61.342	NASSIE 81	REVISION
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		REVISION
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AR
	0		FILTRE CLIM RPLT
15/05/2024	45.466	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE
12/07/2023	41.919	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE
06/02/2023	26.268	SAS INTENSE AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		REVISION
23/01/2023	22.150	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER