MACADAM









BMW 3 Touring: 2CLF168

Vinnumber:	**WBA11FZ060FN45444**	Versionname:	
First Registrationdate:	**1/09/2022**	Fiscalpower:	
Expertise Mileage:	**121517**	Power Kw:	
Bodytype:		Body colour	**Black**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:	**Front**		
Fueltype:	**Hybrid Diesel**		
Maintenance	**NOT OK**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Rear parking sensors	
Windows electric F		Roof bar black	
Windows electric R		Type of Tow bar	**No Tow bar**
Board Computer			
Cruise Control			
Steering wheel multifunctional			
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining artificial leather**		
Type of climate control	**Autom climate control**		
Type of radio	**Multimedia**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/50/17/98 Y**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/50 R 17 98 Y**
Tyre size FR	**225/50 R 17 98 Y**
Tyre size RL	**225/50 R 17 98 Y**
Tyre size RR	**225/50 R 17 98 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**

Total cost ex VAT	**497,01**
Service, Maintenance, Execute	**0,00**



Bumper F, Scratch(es), Repair and paint (complete)	232,99








Alloy rim FL, Scratch(es), Acceptable	0,00




Luggage compartment cover, Missing, Replace	264,02





Bumper R, Scratch(es), Acceptable	0,00





Alloy rim FR, Scratch(es), Acceptable	0,00




Door FR, Scratch(es), Acceptable	0,00




