



BMW X1:

Vinnumber:	WBA31AC0305T28377	Versionname:	sDrive16d (85 kW)
First Registrationdate:	3/03/2021	Fiscalpower:	
Expertise Mileage:	118148	Power Kw:	85
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3425
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection


Tyres

225/55/17/92 H				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 92 H
Tyre size FR				225/55 R 17 92 H
Tyre size RL				225/55 R 17 92 H
Tyre size RR				225/55 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	698,27
Seat cover FL, Damaged, Acceptable	0,00



Door RL, Dent(s), Acceptable		0,00
		
Wing FL, Scratch(es), Acceptable		0,00
		
Wing trim FL, Scratch(es), Acceptable		0,00
		
Alloy rim FL, Scratch(es), Repair and paint (complete)		133,03
		
Bumper R, Scratch(es), Acceptable		0,00
		
Rear window, Scratch(es), Replace		565,24
		
Wing FR, Dent(s), Acceptable		0,00
		
Door FR, Dent(s), Acceptable		0,00
		
Door RR, Dent(s), Acceptable		0,00
		